Sutherlin Festival Grounds

Preliminary Wetland Delineation Report



Assessor's Map 25-05-20, Lot 100

25-05-20AA, Lots 100, 200 and 400

25-05-21, Lots 300 and 400

March 10, 2008

Prepared for

City of Sutherlin
126 East Central Ave.
Sutherlin, OR 97479

Submitted to

Oregon Department of State Lands
775 Summer Street NE, Suite 100
Salem, OR 97301-1279

Department of the Army
Corps of Engineers, Portland District
Eugene Field Office
1600 Executive Parkway, Suite 210
Eugene, Oregon 97401-2156

Prepared by

Satre Associates, P.C.
Planners, Landscape Architects and Environmental Specialists
101 East Broadway, Suite 480
Eugene, Oregon 97401
phone 541.465.4721
fax 541.465.4722
www.satrepc.com

SATRE
ASSOCIATES

WETLAND DELINEATION / DETERMINATION REPORT COVER FORM

This form must be included with any wetland delineation report submitted to the Department of State Lands for review and approval. A wetland delineation report submittal is not "complete" unless the fully completed and signed report cover form and the required fee are submitted. Attach the form to the front of an unbound report and submit to: **Oregon Department of State Lands, 775 Summer Street NE, Suite 100, Salem, OR 97301-1279**

Mail a copy of the completed form with payment of the required report review fee to: **Oregon Department of State Lands, P.O. Box 4395, Unit 18, Portland, OR 97208-4395.**

For new credit card payment option, see DSL web site.

☒ Applicant ☐ Owner Name, Firm and Address: Arthur J. "Bud" Schmidt (City Manager) City of Sutherlin Oregon 126 E. Central Ave, Sutherlin, Oregon 97479	Business phone # (541) 459-2856 ext. 207 Mobile phone # (optional) FAX # E-mail: b.schmidt@ci.sutherlin.or.us
☐ Authorized Legal Agent, Name and Address:	Business phone # FAX # Mobile phone # E-mail:

I either own the property described below or I have legal authority to allow access to the property. I authorize the Department to access the property for the purpose of confirming the information in the report, after prior notification to the primary contact.

Typed/Printed Name: Arthur J Schmidt Signature: _____

Date: Special instructions regarding site access:

Project and Site Information (for latitude & longitude, use centroid of site or start & end points of linear project)

Project Name: Sutherlin Festival Grounds	Latitude: 43° 23.318' N Longitude: 123° 18.467' W
Proposed Use: Formalized Festival Grounds with Rodeo, tractor pull and other activities	Tax Map # 25-5-20AA, 25-5-20, 25-5-21
Project Street Address (or other descriptive location):	Township 25 Range 05 Section [20], [21] QQ Tax Lot (s) {100,100,200,400} [300,400]
City: Sutherlin County: Douglas	Waterway: wetland, Sutherlin creek River Mile: 8.2 NWI Quad(s): Sutherlin

Wetland Delineation Information

Wetland Consultant Name, Firm and Address: Brian Meiering and Susie Holmes Satre Associates P.C. 101 East Broadway Suite 480 Eugene, OR 97401	Phone # 541.465.4721 Mobile phone # 541.844.8883 FAX # 541.465.4721 E-mail: b.meiering@satrepc.com

The information and conclusions on this form and in the attached report are true and correct to the best of my knowledge.

Consultant Signature: Brian Meiering Date: March 30, 2008

Primary Contact for report review and site access is ☒ Consultant ☐ Applicant/Owner ☐ Authorized Agent

Wetland/Waters Present? ☒ Yes ☐ No | Study Area size: 25.9 Acres Total Wetland Acreage: 11.55

Check Box Below if Applicable:	**Fees:**
☐ R-F permit application submitted	☒ Fee payment submitted $ $350.00
☐ Mitigation bank site	☐ Fee ($100) for resubmittal of rejected report
☐ Wetland restoration/enhancement project (not mitigation)	Name of Payor:
☐ Industrial Land Certification Program Site	

Other Information:	Y	N	
Has previous delineation/application been made on parcel?	☐	☒	If known, previous DSL #
Does LWI, if any, show wetland or waters on parcel?	☒	☐	

For Office Use Only

DSL Reviewer: _____	Fee Paid Date: ____/____/____	DSL WD # _____
Date Delineation Received: ____/____/____	DSL Project # _____	DSL Site # _____
Scanned: ☐ Final Scan: ☐	DSL WN # _____	DSL App. # _____

SATRE ASSOCIATES

March 10, 2008

Department of the Army
Corps of Engineers, Portland District
Eugene Field Office
1600 Executive Parkway, Suite 210
Eugene, Oregon 97401-2156

State of Oregon Department of State Lands
775 Summer Street, Suite 100
Salem, Oregon 97301-1279

Re: City of Sutherlin
Arthur J Schmidt
126 East Central Ave.
Sutherlin, OR 97479

Wetland Delineation: Festival Grounds

Dear ODSL and ACOE personnel:

Enclosed please find a Preliminary Wetland Delineation for Sutherlin Festival Grounds. The following materials are included for your review and development plans are anticipated to be submitted within a JPA in the future:

Item:		
Bound herein:	Pages	Copies
Wetland Delineation Text	6	1
Appendix A: Figures 1-5, Sheets 6a-6d	Many	1
Appendix B: Data Forms	Many	1
Appendix C: Ground Level Color Photos	Many	1
Appendix D: Hydrology, Climate and Weather Data	Many	1
Appendix E: Literature Cited	2	1
		1
		1
		1
		1
		1
		1
		1
Total		

To clarify some of the content:

1. This Wetland Delineation has been compiled using the revised wetland delineation format mandated by DSL.

As the applicant's designated contact, Satre Associates is available to answer any questions you may have or provide additional materials if needed. We thank you in advance for your review and consideration of these application materials.

Sincerely,
Brian Meiering

A) **Landscape Setting and Land Use** (previous and current) *OAR141-090-0035 (7)(a)*

The Sutherlin Park Festival Grounds are located within the City of Sutherlin between South State St. west of the site and Southeast Waite Ave east of the site. Sutherlin Creek runs through a ditch comprising the north boundary of the site and the south boundary is comprised of a gravel road (and perimeter ditch) which at one time was a railroad line used by the mining industry and Weyerhaeuser Company. The site is surrounded by low, medium, and high residential, light industrial, and commercial land uses. There is also undeveloped land to the southeast that is zoned for low density residential. The site is currently zoned and used as public open space and conservation land. The site is also host to local gatherings each year consisting of a Stampede Rodeo and Timber Parade Destination and the City's annual Blackberry Festival. Previous land use activities at this site have consisted of an old railroad line running beneath the gravel road abutting the southern edge of the site, and mine tailings were once deposited beneath the existing capped road bed.

B) **Site Alterations** *OAR141-090-0035 (7)(c)*

Alterations have included historic fill (pre 1970's), historic channel alterations (1850s-1960's[4]), damming of Sutherlin creek in the late 1960's-early 1970s[4], and dirt road building in various places throughout the site (South of Sutherlin creek, and just east of western perimeter ditch). According to historic aerial photos the site appeared to be used for agricultural purposes (1939-1960's).

According to local accounts[2] and local watershed assessments[4] drain tiles were installed in the area for local orchards and fields during the late 1890's. Many of these tiles are assumed to have been damaged to date, although the soccer field and some areas surrounding the rodeo may still contain intact drain tiles. The extent and location of tiles is not known.

A road running east-west along the Sutherlin Creek Canal appears[16] to have been constructed around the same time as the Sutherlin creek widening, likely during the 60's[4,16]. It appears to consist primarily of sidecast from the creek widening and a light gravel surface. Other fill was deposited in the eastern area of the site (where the current Ash woodland exists) and may have been related to pre 1970's orchards described in local watershed assessments[4]. This fill also has a small road which connects the old rail line to the south to the Sutherlin creek levee to the north.

The historic railroad line running the southern edge of the site seemed to have been created in the late 1800s in association with the arrival of the O&C Railroad[4] and subsequently abandoned/converted to a roadbed sometime prior to 1982. At one point, the roadbed was capped to reduce metal tailing contamination.

The soccer field in the western portion of the park was built before 1985[2,16] likely using fill deposited there decades before. The property was purchased by the City of Sutherlin in 1988 or 1989[2]. Ditches along the southern boundary of the site were likely established formally when the housing developments went in along the western half of the site in the mid to late 1990's, although local accounts relate the ditches to historic conditions decades ago[2,16]. The rodeo arena and bleachers were installed sometime after 1994, according to aerial photos[16].

During the field investigation, several areas throughout the site seemed to be subject to vehicular use as indicated by muddy rutted areas. When these areas were evident within and around sample plots, evidence was documented on appropriate data sheets (See Appendix B).

C) **Precipitation Data and Analysis** *OAR141-090-0035 (7)(i)*

The average annual precipitation for Roseburg, Oregon (the closest weather data station) is between 29.07 and 37.14 inches [7,13] .Field investigations were done on March 20 and 21, 2007 and on May 2, 8, 10, 2007. Cumulative precipitation for the two weeks prior to the initial survey date (March 20 and 21) was 0.97 inches, with no precipitation occurring on these investigative field days. Cumulative precipitation for the two weeks prior to the May survey dates (2, 8, and 10) was 0.87, 1.37, and 1.37 inches, respectively. Field days had 0.14 inches of precipitation on May 2 and were dry on May 8th and 10th [7]. Percent of normal rainfall year to date was 89.6% by March 1and 78% by May 1. Monthly percent of normal precipitation for each of the three months preceding the field investigations were Dec 110%, Jan 56.4%, Feb 77.5%, Mar 45.0%, Apr 62.0%, and May 34.2% (Percent is per individual month, not a running total).

Subsequent field investigations dates to monitor soil hydrology include February 20, February 26 and March 04. Cumulative precipitation for the two weeks prior to the first survey date (February 20) was 0.2 inches, with no precipitation occurring on this investigative field day. Precipitation on February 26 and March 04 were 0 inches and 0.02 inches, respectively. A running average of normal water year rainfall year to date was 105.8% by February 1 and 91.1% by March 1. Monthly percent of normal precipitation for each of the four months preceding the field investigations were Oct 124.2%, Nov 67.5%, Dec 93.1%, Jan 105.8% and Feb 33.7% (In this case, percent is per individual month, not a running total). Please note that there is a WETS station in Sutherlin but there is no longer a weather station in Sutherlin. The WETS table for Sutherlin was used against weather station recordings from Roseburg station cxus56 kmfr 051000cf6rbg. Please also note that the Sutherlin WETS table doesn't include growing dates. Growing dates were taken from the Roseburg WETS table as it is the nearest and most appropriate second choice.

D) **Methods** (site-specific methods for field investigation, determining wetland boundaries and geographic extent of other waters) *OAR141-090-0030, OAR141-090-0035 (7)(d-e), (g-h), (16)(a-b), (f), (d) or (g), (17), & (19-20)*

Permission was granted by The City of Sutherlin to conduct an on-site investigation of the approximately 25.9 acre study area. The field investigation was conducted in accordance with methodology specified in the Corps Manual[12]. The study area was initially walked to gain familiarity with existing site conditions.

Sampling Points were established at locations that would best characterize the local conditions between upland and wetland areas (See Appendix A, Sheets 6A-6D: Wetland Delineation Maps). At each Sample Point, observations and notes were made regarding vegetative cover, visible hydrology or other indicators of wetland hydrology, and soil characteristics. Visual observations were used to estimate percent vegetative cover for each plant species observed within a 5 foot radius for herbaceous cover and a

30 foot radius for trees and shrubs/saplings. Plots were sized based on local topography and were shaped to meet one condition of particular interest. Data sheets contain specific plot shape information if different from the standard plot type described above. Soil pits were dug to an average depth of 16 inches to observe and describe the soil type, to observe subsurface hydrologic conditions, and to confirm or refute the assigned soil type described in the Soil Survey for Douglas County. Additional observations were made on soil texture, moisture content, and hydric indicators. Examination of aerial photographs and on-site observations were collectively considered when determining the current site hydrology. Photo documentation was conducted to add qualitative information regarding the site and context to this report (See Appendix C: Ground Level Color Photographs).

The majority of plots onsite were considered atypical due to disturbance. Data sheets contain this information and describe what characteristics of wetlands and non-wetlands were used. In the case of the soccer field within the western portion of the study area, an atypical approach was taken to determine whether wetlands were present. After review of past aerial photographs it was determined that this area was filled well before 1972. This led the investigator to not attempt to discern the soil profile below 16 inches from the current profile. Instead, current conditions were judged as the norm and indicators were used as appropriate to judge whether areas were upland or wetland. In this case, indicators of hydrology were the primary factor when making determinations.

The boundary of WL9 was determined using ordinary high water indicators which were readily obvious. An attempt was made to determine the true ordinary high water versus an atypical flood event. Very old rack-lines were evident along the levee of Sutherlin creek and appear to be the product of one or few major flood events. Normal water line deposits containing racks of wood debris were apparent at varying levels along the levee, and the highest of these rack lines with recent deposits was used to determine the boundary. Seasonal drawdown along Sutherlin creek has created an average of 9 feet of wetlands on each side of the creek for the majority of its length through the site. These wetlands are completely contained within the ordinary high water line as delineated.

Initial fieldwork was conducted by Brian Meiering and Susie Holmes (Satre Associates, P C) and all field observations were recorded on data sheets (See Appendix B: Data Forms). Field investigations were done initially on 21 March 2007 and May 2nd, 8th and 10th of 2007 and subsequently on February 20th, 26th and March 4th of 2008 to confirm or refute hydrology. Hydrology monitoring was thought to be necessary due to the atypical complexity of portions of the site containing difficult soils and vegetation. Several dozen soil pits were dug and evaluated at least one time. Necessary plots were chosen based on field conditions and the suitability of previously collected data. All points were mapped using a baseline set of points surveyed in during the original wetland survey. A consistent distance and azimuth were used to field locate plots from surveyed points to within 1 meter. This data was used to confirm, refute and adjust the primary data synthesized in 2007. Please see Appendix D: 2008 Hydrology Data and 2008 Hydrology Monitoring Map.

E) **Description of All Wetlands and Other Non-Wetland Waters** (their characteristics and boundaries, e.g. whether they extend offsite) *OAR141-090-0035 (2), (7)(b), & (17)*

The study area contains nine discernable features with varying degrees of connectivity to each other. These features are mapped and described as WL1 through WL9.

WL1: *0.005 acre pocket wetland within the western portion of the site among historic fill. This wetland is classified as a palustrine emergent seasonally flooded/saturated feature (PEME). This feature more than likely drains south into WL3 beneath fill or evaporates in the early part of the growing season. The boundaries of WL1 were determined primarily based on vegetation and direct observations of hydrology.*

WL2: *0.040 acre pocket wetland within the western portion of the site among historic fill. This wetland is classified as a palustrine emergent seasonally flooded/saturated feature (PEME). This feature more than likely drains south into WL3 beneath fill or evaporates in the early part of the growing season. The boundaries of WL2 were determined based on current vegetation, and current hydric soil indicators and direct observations of hydrology.*

WL3: *0.055 acre linear wetland within the western portion of the site adjacent historic fill and a housing development to the south. This wetland is classified as a palustrine emergent seasonally flooded/saturated feature (PEME). It drains to a standing pipe and into Sutherlin creek just east of the footbridge. It isn't accessible to fish. The boundaries of WL3 were determined primarily based on current vegetation and current indicators of hydrology, and are hydrologically contiguous with WL4.*

WL4: *8.115 acre feature dominating the east central portion of the site and directly connected to WL5, WL3 and WL7. This wetland is classified as a palustrine emergent seasonally flooded/saturated feature (PEME). WL4 is contiguous with WL5. There is no apparent connectivity of WL4 with Sutherlin creek with the possible exception of the water table. It is not accessible to fish as WL7. The boundaries of WL4 were based primarily on hydrology and mapping hydric soils. Vegetation within this wetland was problematic due to the species which were present. Topographical variations due to fill/adjacent development were also used to map the boundary.*

WL5: *0.973 acre feature dominating the east portion of the site and directly connected to WL4 (And is indirectly connected with WL 7 via WL4). This wetland is classified as a palustrine forested seasonally flooded/saturated feature (PFOE). WL4 is contiguous with WL5. There is no apparent connectivity of WL4 with Sutherlin creek with the possible exception of the water table. It is not accessible to fish. The boundaries of WL5 were based on all three parameters of soils, hydrology, and vegetation as well as obvious topographical details due to historic fill.*

WL6: *0.387 acre linear wetland within the southern portion of the site adjacent to the old rail line to the north and a housing development to the south. This wetland is classified as a riverine intermittent unconsolidated bottom seasonally flooded/saturated feature (R4UB6E). It drains west along the rail line and is directly connected in part to off-site wetlands to the south (east of the housing development). The wetland eventually drains west through a culvert along the western boundary of the site and is assumed to drain to Sutherlin creek approximately one*

quarter (1/4) mile to the west. It isn't accessible to fish unless Sutherlin creek flooded extensively.

WL7: *0.077 acre linear wetland within the southern portion of the site adjacent Waite avenue to the east. This wetland is classified as a riverine intermittent unconsolidated bottom seasonally flooded/saturated feature (R2UB6E). It drains to Sutherlin creek. It isn't accessible to fish unless Sutherlin creek flooded extensively.*

WL8: *0.385 acre linear wetland within the southern portion of the site adjacent the old rail line to the south and a housing development to the north. This wetland is classified as a riverine intermittent unconsolidated bottom seasonally flooded/saturated feature(R2UB6E). The wetland eventually drains west through a culvert along the western boundary of the site and is assumed to drain to Sutherlin creek approximately a quarter mile west. A very small segment of palustrine emergent seasonally flooded/saturated has been included within this wetland. WL8 isn't accessible to fish unless Sutherlin creek flooded extensively.*

WL9: *1.808 acre linear wetland within northern portion of the site. This wetland is classified as a riverine permanent unconsolidated bottom semi-permanently flooded feature (R2UB3F). The wetland eventually drains west along the northern boundary of the site. A portion of this wetland as delineated includes the area between the wetland and the ordinary high water line. The ordinary high water contains wetlands in their entirety along the delineated reach. Topography was used extensively to delineate this feature due to its engineered nature. Upstream wetlands and ordinary high water were mapped using paired plots and drift lines indicative of ordinary high water. Ordinary high water was also collected at points downstream. After these points were surveyed, the creek was delineated in between points based on elevation along both sides of the creek. Fish have been documented as using Sutherlin creek including records of coho salmon and winter steelhead[9].*

F) **Deviation from LWI or NWI** (if any, wetland determination data or explanation required.) *OAR141-090-0035 (16)(e)*

Findings are nearly consistent with the Sutherlin Local Wetlands Inventory data. Exceptions include some upland areas around the rodeo arena, the filled eastern edge of the study area near the ash woodland, and some subtle lowland concavities within old fill on soccer field. These areas were confirmed by presence or absence of hydrophytic vegetation and, more importantly, by hydric soil characteristics and direct observations of hydrology.

G) **Mapping Method** (including mapping precision estimate) *OAR141-090-0035 (7)(f), (11), (12), (13), (18), & (22)*

Wetland boundaries were determined using the field investigation methods described above (See Section D: Methods), hydrology data, topography and spot elevation data.

Plot locations and boundaries were marked with flagging for surveyor. Waters of the state and U. S. were delineated by obtaining ordinary high water mark locations and widths along the observed ditches and canals and flags were placed accordingly to inform the surveyor. The survey was performed by registered professional land surveyors, The Dyer Partnership Inc., in June 2007. Precision is estimated at 0.1 foot accuracy for all points and plus or minus 5 feet for boundaries. Digital survey data was managed by Satre Associates using AutoCAD software. The maps produced are at an approximate scale of 1" : 100' (See Appendix A, Sheets 6A-6D).

H) **Additional Information** (i.e., if needed to establish state jurisdiction) *OAR141-085-0015 (1-7), OAR141-090-0030 (2), OAR141-090-0035 (6)(c), (16)(c), & (21)*

Sutherlin creek is accessible to fish, including at least winter steelhead and coho salmon[9]. All other wetlands onsite are not considered accessible to fish except in very high water due to their outfalls into Sutherlin creek. Outfalls typically are five or more feet up the side of the south bank of the Sutherlin creek levee.

I) **Results and Conclusions** *OAR141-090-0035 (7)(j)*

The field study examined the entire Study Area and the presence or absence of wetland indicators and wetland features within the Study Area were documented. The field study identified three (palustrine emergent, palustrine forested, riverine) types of wetlands and a series of jurisdictional waters of the state and U. S within the study area. All sample points and jurisdictional waters are mapped in Sheets 6A-6D.

The field study documented 8.215 acres of *Palustrine Emergent Seasonally Flooded/Saturated* (PEME) wetland. 0.973 acres of *Palustrine Forested Seasonally Flooded/Saturated* (PFOE) wetland, and 2.657 acres of various *Riverine* (R2UB3F, R4UB6E) and jurisdictional waters of the State and U. S.

J) **Disclaimer** *OAR141-090-0035 (7)(k)*

This report of findings includes observations of the project team, relevant information supplied by the client, relevant information supplied by other sources, and documents the best professional judgment of the investigator. This report should be considered a Preliminary Jurisdictional Determination and used at your own risk until it has been reviewed and approved in writing by the Oregon Division of State Lands in accordance with OAR 141-090-0005 through 141-090-0055.



Figure 1: Location Map
USGS 7.5 Minute Quadrangle



Legend

N Study_Area

1 inch equals 325 feet

200 100 0 200 Feet

Appendix A: Maps
Figure 2: Tax Lot Map
Satre Associates 2007



Figure 2B
Central Tax Lot Map



Figure 2C
West Side Tax Lot Map



Figure 2D
East Side Tax Lots



Figure 3a: Local Wetlands Inventory
Sutherlin, Oregon 2001



Figure 3b: National Wetland Inventory
USFWS/USGS 7.5 Minute Quadrangle Data V.2006

Soil Map–Douglas County Area, Oregon
(Sutherlin Festival Grounds)



N

Meters
0 100 200 400 600

Feet
0 450 900 1,800 2,700

USDA Natural Resources Conservation Service

Web Soil Survey 2.0
National Cooperative Soil Survey

Figure 4
Douglas County Soils Map

MAP LEGEND

Area of Interest (AOI)
- Area of Interest (AOI)

Soils
- Soil Map Units

Special Point Features
- Blowout
- Borrow Pit
- Clay Spot
- Closed Depression
- Gravel Pit
- Gravelly Spot
- Landfill
- Lava Flow
- Marsh
- Mine or Quarry
- Miscellaneous Water
- Perennial Water
- Rock Outcrop
- Saline Spot
- Sandy Spot
- Severely Eroded Spot
- Sinkhole
- Slide or Slip
- Sodic Spot
- Spoil Area
- Stony Spot
- Very Stony Spot
- Wet Spot
- Other

Special Line Features
- Gully
- Short Steep Slope
- Other

Water Features
- Oceans

Transportation
- Rails

MAP INFORMATION

Original soil survey map sheets were prepared at publication scale. Viewing scale and printing scale, however, may vary from the original. Please rely on the bar scale on each map sheet for proper map measurements.

Source of Map: Natural Resources Conservation Service
Web Soil Survey URL: http://websoilsurvey.nrcs.usda.gov
Coordinate System: UTM Zone 10N

This product is generated from the USDA-NRCS certified data as of the version date(s) listed below.

Soil Survey Area: Douglas County Area, Oregon
Survey Area Data: Version 7, Dec 22, 2006

Date(s) aerial images were photographed: 5/7/1994

The orthophoto or other base map on which the soil lines were compiled and digitized probably differs from the background imagery displayed on these maps. As a result, some minor shifting of map unit boundaries may be evident.

Map Unit Legend

Douglas County Area, Oregon (OR649)			
Map Unit Symbol	Map Unit Name	Acres in AOI	Percent of AOI
44A	Conser silty clay loam, 0 to 3 percent slopes	153.7	91.2%
215E	Rosehaven loam, 12 to 30 percent slopes	0.2	0.1%
224B	Sibold fine sandy loam, 0 to 5 percent slopes	4.0	2.4%
235C	Sutherlin silt loam, 3 to 12 percent slopes	10.5	6.3%
Totals for Area of Interest (AOI)		168.4	100.0%

N

Legend

Study_Area

1 inch equals 325 feet

325 162.5 0 325 Feet

Figure 5a
1939 Aerial Photograph
Sutherlin Festival Grounds
Source: U of O Map Library

N

Legend

Study_Area

1 inch equals 325 feet

325 162.5 0 325 Feet

Figure 5b
1943 Aerial Photograph
Sutherlin Festival Grounds
Source: U of O Map Library

N

Legend

Study_Area

1 inch equals 325 feet

325 162.5 0 325 Feet

Figure 5c
1950 Aerial Photograph
Sutherlin Festival Grounds
Source: U of O Map Library

N

Legend

Study_Area

1 inch equals 325 feet

325 162.5 0 325 Feet

Figure 5d
1952 Aerial Photograph
Sutherlin Festival Grounds
Source: U of O Map Library



N

Legend

Study_Area

1 inch equals 325 feet

325 162.5 0 325 Feet

Figure 5e
1960 Aerial Photograph
Sutherlin Festival Grounds
Source: U of O Map Library

N

Legend

Study_Area

1 inch equals 325 feet

325 162.5 0 325 Feet

Figure 5f
1967 Aerial Photograph
Sutherlin Festival Grounds
Source: U of O Map Library



N

Legend

Study_Area

1 inch equals 325 feet

325 162.5 0 325 Feet

Figure 5g
1979 Aerial Photograph
Sutherlin Festival Grounds
Source: U of O Map Library



Legend

Study_Area

1 inch equals 325 feet

325 162.5 0 325 Feet

Figure 5h
1982 Aerial Photograph
Sutherlin Festival Grounds
Source: U of O Map Library



N

Legend

Study_Area

1 inch equals 325 feet

325 162.5 0 325 Feet

Figure 5i
1983 Aerial Photograph
Sutherlin Festival Grounds
Source: U of O Map Library



N

Legend

Study_Area

1 inch equals 325 feet

325 162.5 0 325 Feet

Figure 5j
1985 Aerial Photograph
Sutherlin Festival Grounds
Source: U of O Map Library



N

Legend

Study_Area

1 inch equals 325 feet

325 162.5 0 325 Feet

Figure 5k
1989 Aerial Photograph
Sutherlin Festival Grounds
Source: U of O Map Library

N

Legend

Study_Area

1 inch equals 325 feet

325 162.5 0 325 Feet

Figure 5l
1994 Aerial Photograph
Sutherlin Festival Grounds
Source: U of O Map Library

N

Legend

Study_Area

1 inch equals 325 feet

325 162.5 0 325 Feet

Figure 5m
2001 Aerial Photograph
Sutherlin Festival Grounds
OGDC Downloaded 2007



N

Legend

Study_Area

1 inch equals 325 feet

325 162.5 0 325 Feet

Figure 5n
2004 Aerial Photograph
Sutherlin Festival Grounds
USDA NAIP 2004

NARRATIVE

THE PURPOSE OF THIS SURVEY IS TO TIEOUT WETLAND FEATURES FOR USE BY THE CITY OF SUTHERLIN AND SATRE ASSOCIATES. WETLAND FLAGS WERE ESTABLISHED BY SATRE ASSOCIATES.

THIS SITE INVOLVES THE FAIRGROUNDS AREA.

NO PROPERTY CORNERS WERE SET DURING THIS SURVEY.

HORIZONTAL CONTROL
HORIZONTAL CONTROL UTILIZES NAD 83/98 OREGON STATE PLANE - SOUTH. CONTROL IS BASED ON NGS STATION UMPQUA NE BASE (PID PC1022).
VALUES PER NGS FOR THIS STATION ARE AS FOLLOWS:
LATITUDE:: 43 23 45.11454 (N) LONGITUDE: 123 19 52.91029 (W).

MONUMENT IS LOCATED JUST WEST OF COMSTOCK ROAD AND APPROX. 0.6 MILES NORTH OF CENTRAL AVENUE.

VERTICAL DATUM
1988 NAVD. BENCH MARK USED IS NGS STATION X 739 (PID PC0746).
RECORD ELEVATION = 544.58 FEET.

BENCH MARK IS LOCATED BY RR TRACKS AT 6TH & STATE STREET INTERSECTION.

HORIZONTAL AND VERTICAL CONTROL WERE ESTABLISHED USING TRIMBLE R6 GPS EQUIPMENT USING RTK METHOD HOLDING ABOVE HORIZONTAL AND VERTICAL CONTROL POINTS.

EQUIPMENT USED
GPS TRIMBLE R6 WITH GLNSS
LEICA TC1010 TOTAL STATION
SURVEY SOFTWARE: TRIMBLE GEOMATICS AND LISCAD



VICINITY MAP
(NOT TO SCALE)

LOCATED IN SECTIONS 16, 17, 20 & 21, TOWNSHIP 25 SOUTH, RANGE 5 WEST, W.M., DOUGLAS COUNTY, OREGON

INDEX TO DRAWINGS

Drawing No.	Description
S1	Index, Legend, Vicinity Map & Narrative Sheet
S2	WEST SECTION - SITE MAP
S3	MIDDLE SECTION - SITE MAP
S4	EAST SECTION - SITE MAP

LEGEND

R-O-W/PROPERTY LINE		EVERGREEN TREE	
WETLAND FLAG		DECIDUOUS TREE	
CURB & GUTTER W/ SIDEWALK		BRUSHLINE	
CATCH BASIN	CB	DITCH LINE	
STORM DRAIN MANHOLE	SD	EDGE OF PAVEMENT	
SEWER MANHOLE	S	EDGE OF GRAVEL	
WATER VALVE	WV	FENCE LINE	
FIRE HYDRANT	FH	UTILITY POLE W/ GUY ANCHOR	
BLOWOFF	BO	BUILDING	
WATERLINE	W	CLEANOUT	CO
SEWERLINE			
CULVERT/STORM DRAIN LINE			
MAJOR CONTOUR			
MINOR CONTOUR			

SATRE ASSOCIATES, P.C.
Planners, Landscape Architects & Environmental Specialists
101 East Broadway, Suite 410
Eugene, Oregon 97401
(541) 465-4721 - Fax (541) 465-4722 - 1-800-662-7094
www.satreassoc.com

NOTES:

THE FOLLOWING LABELS & SYMBOLS WERE ADDED TO THIS DRAWING SET TO CLARIFY THE LOCALITIES OF ON SITE WETLANDS:

	LABEL	SYMBOL
WETLAND:	WLX	
SAMPLE PLOT:	SPX	
HYDROLOGY MONITORING PLOT:	HX	

DRAWING NO. S1
SHEET NO. 1 OF 4
PROJECT NO. 145.15
DATE JUNE, 2007

CITY OF SUTHERLIN
FAIRGROUND WETLAND SURVEY

INDEX, LEGEND, VICINITY MAP & NARRATIVE SHEET

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 14, 1989 MICHAEL W. ERICKSON 2345 EXPIRES: 12-31-07

THE DYER PARTNERSHIP ENGINEERS & PLANNERS, INC.
1330 TEAKWOOD AVENUE
COOS BAY, OREGON 97420
TELEPHONE: (541) 269-0732
www.dyerpart.com

LINES 2 INCHES AT FULL SCALE
IF NOT 2" - SCALE ACCORDINGLY

SATRE ASSOCIATES
Planners, Landscape Architects & Environmental Specialists

SHEET 6A



SHEET 6B

Planning, Landscape Architecture & Environmental Specialists

THE DYER PARTNERSHIP
ENGINEERS & PLANNERS, INC.
1330 TEAKWOOD AVENUE
COOS BAY, OREGON 97420
TELEPHONE: (541) 269-0732
www.dyerpart.com

LINE IS 2 INCHES AT FULL SCALE
IF NOT 2" - SCALE ACCORDINGLY

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 24, 1981
MICHAEL W. ERICKSON
2340
EXPIRES: 12-31-07

CITY OF SUTHERLIN
FAIRGROUND WETLAND SURVEY

WEST SECTION - SITE MAP

PROJECT NO.	DRAWING NO.
146.15	S2
DATE	SHEET NO.
JUNE, 2007	2 OF 4



SHEET 6C	THE DYER PARTNERSHIP ENGINEERS & PLANNERS, INC. 1330 TEAKWOOD AVENUE COOS BAY, OREGON 97420 TELEPHONE: (541) 269-0732 www.dyerpart.com	REGISTERED PROFESSIONAL LAND SURVEYOR	CITY OF SUTHERLIN FAIRGROUND WETLAND SURVEY	PROJECT NO. 146.15	DRAWING NO. S3
	LINE IS 2 INCHES AT FULL SCALE IF NOT 2" - SCALE ACCORDINGLY	OREGON JULY 19, 1988 MICHAEL W. ERICKSON 2340 EXPIRES: 12-31-07	MIDDLE SECTION - SITE MAP	DATE JUNE, 2007	SHEET NO. 3 OF 4

SHEET 6D

Natural Landscape Architects & Environmental Specialists

THE DYER PARTNERSHIP
ENGINEERS & PLANNERS, INC.
1330 TEAKWOOD AVENUE
COOS BAY, OREGON 97420
TELEPHONE: (541) 269-0732
www.dyerpart.com

LINE IS 2 INCHES AT FULL SCALE
IF NOT 2" - SCALE ACCORDINGLY

REGISTERED PROFESSIONAL LAND SURVEYOR
OREGON
JULY 19, 1983
MICHAEL W. ERICKSON
2310
EXPIRES: 6-30-07

CITY OF SUTHERLIN
FAIRGROUND WETLAND SURVEY

EAST SECTION - SITE MAP

PROJECT NO.	DRAWING NO.
146.15	S4
DATE	SHEET NO.
JUNE, 2007	4 OF 4

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 21/March/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meierino/ Susie Holmes
Plant Community: Disturbed/ Compacted Roadside Ditch Plot # SP1
Plot location: Just east of S State St. north of dirt road in ditch
Recent Weather: Mean temp ~44 degrees partly cloudy, 1.05 " month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☒ Soil ☒ Hydrology ☒ been significantly disturbed?
Explain: Plot is located within a roadside, man-made ditch with compacted soils and diverted hydrology. Site is altered by adjacent development, and previous fill activities. Roadside built well before 1972.

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1. Rubus armeniacus*	FACU- 40 100
2.	
3.	
4.	
5.	

Herb Stratum

	Status/ Raw % Cover/ Rel % Cover
1. Festuca arundinacea*	FAC- 30 27
2. Holcus lanatus*	FAC 25 23
3. Hypochaeris radicata*	FACU 20 18
4. Daucus carota*	NOL 20 18
5. Centaurea pratensis	NOL 15 14
6.	
7.	
8.	
9.	
10.	
11.	

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 20%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☐ NO ☒ Comments: Vegetation not used in determination (due to atypical nature of ditch)

SOILS

Map Unit Name: 44 A Conser Silty Clay Loam Drainage Class: Poorly Drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0-5"	5yr 5/2-3	7.5yr 6/8 @ 5" C/M/D/ Matrix	SCL w/fill
	Refusal at 5"		

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☒ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☒ NO ☐ Comments: Soils in this area are fairly red at times due to historic red tailings, although mottling was obvious.

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☒ Drift Lines
- ☒ Sediment Deposits
- ☒ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☒ NO ☐ Comments: Perimeter ditch has obvious high water marks.

DETERMINATION

WETLAND? YES ☒ NO ☐ **Comments:** Hydrology evident to driftlines as ordinary high water. Atypical excavated ditch is well defined by elevation gradient. This plot very weedy. Hydrology evidence is strong and the normal circumstance points to wetland characteristics throughout the extent of the ditch.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 21/March/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Disturbed/ Compacted Roadside Plot # SP2
Plot location: Just south/upland of SP1
Recent Weather: Mean temp ~44 degrees partly cloudy, 1.05 " month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☒ Soil ☒ Hydrology ☒ been significantly disturbed?
Explain: Plot is located along the shoulder of a roadside, just above a man-made ditch with compacted soils and diverted hydrology, site is altered by adjacent development, and previous fill activities. Rail line built well before 1972.

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover		
1. Rubus armeniacus*	FACU-	t	t
2. Rosa cf. eglanteria*	FACW	t	t
3.			
4.			
5.			

Herb Stratum

	Status/ Raw % Cover/ Rel % Cover		
1. Avena cf. fatua*	NOL	60	57
2. Festuca arundinacea *	FAC-	25	24
3. Hypochaeris radicata	FACU	6	6
4. Daucus carota	NOL	5	5
5. Centaurea pratensis	NOL	5	5
6. Vicia sativa var. sativa	NOL	5	5
7.			
8.			
9.			
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 20%
Other Hydrophytic Vegetation Indicators: None
Criteria Met? YES ☐ NO ☒ Comments: Roadbed

SOILS

Map Unit Name: Conser silty clay loam Drainage Class: Poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* * abund./size/contrast/color/location (matrix or pores/peds)	Redox Depletions*	Texture
Refusal				Gravel

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☐ NO ☒ Comments: Atypical, road bed is capped with gravel from old rail line.

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: 0 Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☐ NO ☒ Comments: ____

DETERMINATION

WETLAND? YES ☐ NO ☒ **Comments:** Plot taken to describe capped roadway bisecting perimeter ditch.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 21/March/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Disturbed/ Compacted Roadside Ditch Plot # SP3
Plot location: Just west of first house on the south side of central street with culdesac, within central ditch
Recent Weather: Mean temp ~44 degrees partly cloudy, 1.05 " month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: _____
Has Vegetation ☐ Soil ☐ Hydrology ☐ been significantly disturbed?
Explain: _____

VEGETATION

Tree Stratum

	Status/	Raw % Cover/	Rel % Cover
1. Crataegus monogyna*	FACU+	25	50
2. Fraxinus latifolia*	FACW	20	40
3. Malus cf X domestica	UPL	5	10

Sapling/Shrub Stratum

	Status/	Raw % Cover/	Rel % Cover
1. Crataegus monogyna*	FACU+	15	100
2.			
3.			
4.			
5.			

Herb Stratum

	Status/	Raw % Cover/	Rel % Cover
1. Festuca arundinacea*	FAC-	60	53
2. Juncus patens*	FACW	25	22
3. Mentha pulegium	OBL	8	7
4. Daucus carota	UPL	5	4
5. Centaurea pratensis	UPL	5	4
6. Dipsacus fullonum ssp sylvestris	FAC	5	4
7. Geranium dissectum	UPL	t	t
8. Taraxicum officianale	FACU	t	t
9.			
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 12/5%
Other Hydrophytic Vegetation Indicators: see non-dominants within herb stratum list. NOL species occurred around the periphery of plot and weren't indicative of plot center so were therefore omitted from the 50/20
Criteria Met? YES ☐ NO ☒ Comments: Festuca arundinaceae AND Crataegus monogyna (possible hybrid) problematic. Veg would have passed without it. Crataegus cover shouldn't be equally weighted because it was truly not dominant.

SOILS

Map Unit Name: Conser silty clay loam Drainage Class: Poorly Drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0 - 16"	10yr 3/2 - 1	5yr 6/8 C/F/D @ 9"	SCL

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☒ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): _____

Criteria Met? YES ☒ NO ☐ Comments: Mottling begins within 3"

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: 0 Depth to Saturation: 8" Depth to free water: 9.5"

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☒ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: _____

Criteria Met? YES ☒ NO ☐ Comments: Hydrology provided by perimeter ditch.

DETERMINATION

WETLAND? YES ☒ NO ☐ Comments: Although vegetation is somewhat problematic, hydrology + soils are strongly suggestive of wetland characteristics

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 21/March/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Disturbed/ Compacted Roadside Plot # SP4
Plot location: Just south/upland of SP3
Recent Weather: Mean temp ~44 degrees partly cloudy, 1.05 " month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: _____
Has Vegetation ☒ Soil ☒ Hydrology ☒ been significantly disturbed?
Explain: Plot is located along the shoulder of a roadside, just above a ditch with compacted soils and diverted hydrology, site is altered by and previous fill activities. Rail line built well before 1972.

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status/ Raw % Cover/ Rel % Cover		
1. Festuca arundinacea*	FAC-	80	76
2. Holcus lanatus*	FAC	5	5
3. Hypochaeris radicata*	FACU	5	5
4. Daucus carola*	NOL	5	5
5. Centaurea pratensis*	NOL	5	5
6. Dipsacus follonum ssp sylvestris*	FAC	5	5
7. Trifolium repens	FACU+	t	t
8. Vicia sativa var. sativa	NOL	t	t
9. Rumex crispus	FAC+	t	t
10. Rumex acetosella	FACU+	t	t
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 33%
Other Hydrophytic Vegetation Indicators: _____
Criteria Met? YES ☐ NO ☒ Comments: Community is disturbed FAC dominant

SOILS

Map Unit Name: Conser silty clay loam Drainage Class: Poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations*	Redox Depletions*	Texture
		* abund./size/contrast/color/location (matrix or pores/peds)		
	Refusal @ 0"			

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): _____

Criteria Met? YES ☐ NO ☒ Comments: Atypical- Gravel roadbed edge

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: _____

Criteria Met? YES ☐ NO ☒ Comments: Same as soil commentary

DETERMINATION

WETLAND? YES ☐ NO ☒ **Comments:** Gravel roadbed edge. Hasn't been recently disturbed. (Plot taken to describe rail line edge.)

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 21/March/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Melering/ Susie Holmes
Plant Community: Ash Woodland Plot # SP5
Plot location: Plot is along western side of eastern ash woodland area
Recent Weather: Mean temp ~44 degrees partly cloudy, 1.05 " month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☐ Soil ☐ Hydrology ☐ been significantly disturbed?
Explain: ____

VEGETATION

Tree Stratum

	Status	Raw % Cover	Rel % Cover
1. Fraxinus latifolia*	FACW	90	100
2.			
3.			

Sapling/Shrub Stratum

	Status	Raw % Cover	Rel % Cover
1. Crataegus monogyna*	FACU+	50	100
2.			
3.			
4.			
5.			

Herb Stratum

	Status	Raw % Cover	Rel % Cover
1. Carex densa*	OBL	20	20
2. Juncus patens*	FACW	20	20
3. Lathyrus aphaca*	UPL	15	15
4. Fraxinus latifolia*	FACW	15	15
5. Camassia cf. quamash*	FACW	15	15
6. Lathyrus sylvestris	NOL	10	10
7. Mentha pulegium	OBL	5	5
8. Sanicula crassicaulis	NOL	t	t
9. Daucus carota	NOL	t	t
10. Cardamine oligosperma	FAC	t	t
11. C. penduliflora	OBL	t	t

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 80%
Other Hydrophytic Vegetation Indicators: see list of non-dominants under herb stratum
Criteria Met? YES ☒ NO ☐ Comments: Also passes FAC-Neutral test

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: Poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* * abund./size/contrast/color/location (matrix or pores/peds)	Redox Depletions*	Texture
0 - 8"	2.5yr 4/1	7.5yr 6/8		SCL
8 - 16"	5yr 3/1	7.5 yr 6/8	10yr 6/1	SC
16 - 20	10yr 6/1	-----	---	C

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☒ Gleyed or low chroma colors
- ☒ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☒ NO ☐ Comments: ____

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: 0 Depth to Saturation: 7" Depth to free water: 8"

Primary Hydrology Indicators:
- ☐ Inundated
- ☒ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☒ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☒ NO ☐ Comments: ____

DETERMINATION

WETLAND? YES ☒ NO ☐ **Comments:** This was one of the least disturbed of the plots. Plot taken to describe least altered condition within eastern ash stand. Established a baseline to judge historic fill that occurred to the east (pre-70's) and to differentiate the disturbed western field

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 21/March/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Wet Meadow Plot # SP6
Plot location: Plot is just west of ash woodland area in open, inundated meadow
Recent Weather: Mean temp ~44 degrees partly cloudy, 1.05 " month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☐ Soil ☐ Hydrology ☐ been significantly disturbed?
Explain: meadow is a muddy pit that has repeatedly been driven through, although this area was somewhat spared

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status	Raw % Cover	Rel % Cover
1. Hordeum jubatum*	FAC	50	50
2. Glyceria occidentalis*	OBL	20	20
3. Mentha pulegium*	OBL	20	20
4. Juncus marginatus	NOL	10	10
5. Camassia cf. quamash	FACW	t	t
6. Parentucellia viscosa	FAC-	t	t
7. Lathyrus sphaericus	NOL	t	t
8. Lolium perenne	FAC	t	t
9. Festuca arundinacea	FAC-	t	t
10. Ranunculus occidentalis	FAC	t	t
11. Luzula multiflora	FACU	t	t

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 100%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☒ NO ☐ Comments: 25% of plot is standing water(plot exemplary example of undisturbed vegetation relative to other plants in eastern field.) (Juncus marginatus has national indicator status of at least FACW.)

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: Pourly drained

On Hydric Soils List? Y ☐ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0 - 8	2.5yr 3/1	10yr 7/8 C/F/D/M,po,pe	SCL
8 - 18	10yr 6/1	F/F/F	C

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☒ Gleyed or low chroma colors
- ☒ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☒ NO ☐ Comments: Possibly the lesser of disturbed soil profiles on site

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: 0 Depth to Saturation: To surface Depth to free water: 2"

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☒ Sediment Deposits
- ☒ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☒ NO ☐ Comments: From this point westward, atypical situtations are the norm.

DETERMINATION

WETLAND? YES ☒ NO ☐ **Comments:** Plot is just east of the beginning of standing water. (Soil profile of this plot is typical of open field, within common vehicular disturbance.)

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 02/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Grassy Lawn/ Meadow Plot # SP7
Plot location: Along northern central edge of soccer field within a slight topographic depression
Recent Weather: Mean temp 50~degrees, partly cloudy, 0.14" percipitation, 0.34" month to date percipitation
Do normal environ. conditions exist? Y ☐ N ☒ If No, explain: Site was recently mowed (typical of management)
Has Vegetation ☒ Soil ☒ Hydrology ☐ been significantly disturbed?
Explain: plants are still recognizable regardless of recent mowing

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status/ Raw % Cover/ Rel % Cover		
1. Mentha pulegium	OBL	65	42
2. Hordeum jubatum	FAC	60	39
3. Plagiobothrys cf. figuratis	FACW	20	13
4. Poa annua	FAC	3	2
5. Rumex crispus	FAC+	3	2
6. Hypochaeris radicata	FACU	3	2
7.			
8.			
9.			
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 100%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☒ NO ☐ Comments: ____

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: Poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0 - 1"	7.5yr 3/3		
2 - 4"	10yr 5/3	5yr 6/8 C/M/D/matrix/pds	B/G
4 - 9"	10yr 3/3	5yr 5/8 C/M/D/	B/G
9 - 17"	2.5yr 2.5/1	7.5yr 5/8 C/F/D	SCL

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☒ Gleyed or low chroma colors
- ☒ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☒ NO ☐ Comments: 9 - 7" 13 old (apparently native) (9-11" organic O horizon)

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: 0 Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☒ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☒ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☒ NO ☐ Comments: ____

DETERMINATION

WETLAND? YES ☒ NO ☐ **Comments:** S Fill within field needs to be established as to the date it was placed [see 3 Dec. 2008 TELCON with J. Carnate.]. Soccer field built (filled) before 1985 according to local accounts, but was more than likely filled much earlier originally.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 02/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Grassy Lawn/ Meadow Plot # SP8
Plot location: East-northeast off the corner of SP7
Recent Weather: Mean temp 50~degrees, partly cloudy, 0.14" percipitation, 0.34" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☒ Soil ☒ Hydrology ☐ been significantly disturbed?
Explain: Site was recently mowed (typical of management), although plants are still recognizable regardless of recent mowing

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status/	Raw % Cover/	Rel % Cover
1. Festuca arundinacea*	FAC-	95	81
2. Trifolium repens*	FACU+	10	8
3. Bellis perennis*	NOL	8	7
4. Stellaria media*	FACU	5	4
5. Hypochaeris radicata	FACU	t	t
6. Rumex crispus	FAC+	t	t
7.			
8.			
9.			
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 0%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☐ NO ☒ Comments: atypical mowed weedy field...plants identifieable regardless of mowing. Used all species greater than trace due to the almost monoculture vegetation structure of fest. arund.

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: Poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0 - 7"	10.5yr 3/2	Negligible	SCL+fill
Refusal@7"	due to fill		

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☐ NO ☒ Comments: ____

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☐ NO ☒ Comments: Topographically slightly above sp7

DETERMINATION

WETLAND? YES ☐ NO ☒ **Comments:** Fill here is more inpenitrable due to larger rock. Plot impacted by pre-1972 slope fill due to sidecast and levee construction. see sp 7 notes.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 02/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Grassy Lawn/ Meadow Plot # SP9
Plot location: Western edge of SP7
Recent Weather: Mean temp 50~degrees, partly cloudy, 0.14" percipitation, 0.34" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☒ Soil ☒ Hydrology ☐ been significantly disturbed?
Explain: Site was recently mowed (typical of management), although plants are still recognizable regardless of recent mowing

VEGETATION

Tree Stratum

Status/ Raw % Cover/ Rel % Cover

1. ____
2. ____
3. ____

Sapling/Shrub Stratum

Status/ Raw % Cover/ Rel % Cover

1. ____
2. ____
3. ____
4. ____
5. ____

Herb Stratum

	Status/	Raw % Cover/	Rel % Cover
1. Festuca arundinacea*	FAC-	90	83
2. Trifolium repens*	FACU+	10	9
3. Poa annua*	FAC	5	5
4. Plantago lanceolata*	FACU+	3	3
5. Hypochaeris radicata	FACU	t	t
6. Rumex crispus	FAC+	t	t
7. Taraxicum officianale	FACU	t	t
8. Trifolium subterranium	NOL	t	t
9. ____			
10. ____			
11. ____			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 0%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☐ NO ☒ Comments: Used all significant vegetation to calculate dominance due to weed, seeded field.

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: Poorly Drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* * abund./size/contrast/color/location (matrix or pores/peds)	Redox Depletions*	Texture
0 - 12"	10yr 4/3	None		

refusal due to

Hydric Soil Indicators:

- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☐ NO ☒ Comments: Fill needs to be penetrated to reach native profile.

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:

- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):

- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☐ NO ☒ Comments: ____

DETERMINATION

WETLAND? YES ☐ NO ☒ **Comments:** Fill either originally deeper or has settled less than SP7 due to differentiated water table. Need to monitor hydrology to finalize unless fill can be established earlier than CWA.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 02/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Grassy Lawn/ Meadow Plot # SP10
Plot location: Western end of soccer field just northwest of goal posts
Recent Weather: Mean temp 50~degrees, partly cloudy, 0.14" percipitation, 0.34" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: _____
Has Vegetation ☒ Soil ☒ Hydrology ☐ been significantly disturbed?
Explain: Site was recently mowed (typical of management), although plants are still recognizable regardless of recent mowing. Soil profile seems intact below fill

VEGETATION

Tree Stratum

	Status	Raw % Cover	Rel % Cover
1.			
2.			
3.			

Sapling/Shrub Stratum

	Status	Raw % Cover	Rel % Cover
1.			
2.			
3.			
4.			
5.			

Herb Stratum

	Status	Raw % Cover	Rel % Cover
1. Festuca arundinacea *	FAC-	70	56
2. Mentha pulegium *	OBL	30	24
3. Hordeum jubatum *	FAC	20	16
4. Poa annua *	FAC	5	4
5. Rumex crispus *	FAC+	t	t
6.			
7.			
8.			
9.			
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 80%
Other Hydrophytic Vegetation Indicators: _____
Criteria Met? YES ☒ NO ☐ Comments: Used all vegetation due to lack of tree + shrub layers.

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: Poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0-1"	7.5yr 3/3		
2-4"	10yr 5/3	5yr 6/8 C/M/D/matrix/pds	B/G
4 - 8"	10yr 3/3	5yr 5/8 C/M/D	B/G
8 - 17"	7.5yr 5/8 C/F/D		SCL

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☒ Gleyed or low chroma colors
- ☒ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☒ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): _____

Criteria Met? YES ☒ NO ☐ Comments: Plot is slightly less distrubed portion of field near fenceline. Due to non-native soil profile this was considered hydric.

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☒ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☒ FAC-Neutral Test
- ☐ Other: _____

Criteria Met? YES ☒ NO ☐ Comments: _____

DETERMINATION

WETLAND? YES ☒ NO ☐ **Comments:** This is an insignificant area and is negligible unless considered contiguous beneath fill across entire soccer field. Vegetation and hydrology strong within atypical plot. See sp 7 notes on fill date.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 02/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Grassy Lawn/ Meadow Plot # SP11
Plot location: Northwest corner of soccer field within a slight topographic depression
Recent Weather: Mean temp 50~degrees, partly cloudy, 0.14" percipitation, 0.34" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☒ Soil ☒ Hydrology ☐ been significantly disturbed?
Explain: Site was recently mowed (typical of management), although plants are still recognizable regardless of recent mowing

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status	Raw % Cover	Rel % Cover
1. Hordeum jubatum *	FAC	25	33
2. Mentha pulegium *	OBL	22	29
3. Plagiobothrys cf. figuratis *	FACW	18	24
4. Poa annua	FAC	5	7
5. Festuca arundinacea	FAC-	3	4
6. Agrostis cf. tenuis	FAC	3	4
7. Medicago polymorpha	NOL	t	t
8. Taraxicum officianale	FACU	t	t
9. Plantago lanceolata	FACU+	t	t
10. Ludwigia palustris	OBL	t	t
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 100%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☒ NO ☐ Comments: Used top 3 species due to likelihood of any difference btw figuratus and pulegium % cover.

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* * abund./size/contrast/color/location (matrix or pores/peds)	Redox Depletions*	Texture
0 - 6"	10yr 3/3	5yr 6/8 soft masses	C/D/M=1%	SCL+fill
6 - 16"	2.5yr 3/2	5yr 6/8 soft masses	C/D/M=5%	SCL+fill

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☒ Gleyed or low chroma colors
- ☒ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☒ NO ☐ Comments: Profile is fill to 6" - old horizon visible at 6-7

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☒ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☒ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☒ NO ☐ Comments: ____

DETERMINATION

WETLAND? YES ☒ NO ☐ Comments: This area is insignificant and negligible unless considered contiguous beneath fill across entire soccer field. See sp7 notes on fill.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 02/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Grassy Lawn/ Meadow Plot # SP12
Plot location: Just upland and northeast of SP11 in northwest corner of soccer field
Recent Weather: Mean temp 50-degrees, partly cloudy, 0.14" percipitation, 0.34" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☒ Soil ☐ Hydrology ☐ been significantly disturbed?
Explain: Site was recently mowed (typical of management), although plants are still recognizable regardless of recent mowing

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status/	Raw % Cover/	Rel % Cover
1. Stellaria media *	FACU	25	26
2. Festuca arundinacea*	FAC-	20	20
3. Poa annua*	FAC	20	20
4. Taraxicum officianale	FACU	10	10
5. Hordeum jubatum	FAC	10	10
6. Plantago lanceolata	FACU+	5	5
7. Trifolium subterraneum	FACU+	t	t
8. Bellis perennis	NOL	t	t
9.			
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 33%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☐ NO ☒ Comments: ____

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: Poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0 - 6	10yr 3/3		Fill
6 - 16	2.5yr 3/2		SCL

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☐ NO ☒ Comments: ____

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: 0 Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☐ NO ☒ Comments: ____

DETERMINATION

WETLAND? YES ☐ NO ☒ **Comments:** Represents deeper fill and lack of hydrology w/in 12". Fill from road along Sutherlin Creek is from levee, not from field fill. Levee appears to be built from side cast material from Sutherlin Creek. BPJ debates that this plot represents the edge of fill from levee and beginning of fill from the soccer field.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 02/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Grassy Lawn/ Meadow Plot # SP13
Plot location: East-southeast of eastern goal of soccer field
Recent Weather: Mean temp 50~degrees, partly cloudy, 0.14" percipitation, 0.34" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: _____
Has Vegetation ☐ Soil ☐ Hydrology ☐ been significantly disturbed?
Explain: _____

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status/ Raw % Cover/ Rel % Cover		
1. Festuca arundinacea *	FAC-	30	24
2. Agrostis cf. tenuis *	FAC	30	24
3. Juncus marginatus *	UPL	15	12
4. Juncus ensifolius *	FACW	15	12
5. Hordeum jubatum *	FAC	10	8
6. Glyceria occidentalis *	OBL	10	8
7. Carex densa *	OBL	10	8
8. Vicia sativa var. sativa	UPL	3	2
9. Trifolium subterraneum	FACU+	t	t
10. Rumex crispus	FAC+	t	t
11. Ranunculus occidentalis	FAC	t	t

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 71%
Other Hydrophytic Vegetation Indicators: _____
Criteria Met? YES ☒ NO ☐ Comments: Used top 7 dominant species due to lack of other stratum.

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: Poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0 - 9"	10yr 3/2	5yr 5/8 C/M/D	SCL
10 - 26"	10yr 2.5/1	Too different to dist	SC

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☒ Gleyed or low chroma colors
- ☒ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): _____

Criteria Met? YES ☒ NO ☐ Comments: Probably a more typical soil - outside fill from soccer field.

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☒ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☒ FAC-Neutral Test
- ☐ Other: _____

Criteria Met? YES ☒ NO ☐ Comments: Hydrology may be caused by fill in SP14, now a normal environmental circumstance..

DETERMINATION

WETLAND? YES ☒ NO ☐ Comments: Seasonal wetland constricted by historic fill to north. This section of wetland marked by distinct fall out of Juncus Spp. in upland and district fill pattern, apparent in photographs as pre-1972..

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 02/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Open Meadow Plot # SP14
Plot location: ~15 ft north of plot center of SP13
Recent Weather: Mean temp 50-degrees, partly cloudy, 0.14" percipitation, 0.34" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☒ Soil ☒ Hydrology ☒ been significantly disturbed?
Explain: ____

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status/ Raw % Cover/ Rel % Cover		
1. Festuca arundinacea *	FAC-	80	68
2. Bromus mollis *	UPL	20	17
3. Daucus carota	NOL	5	4
4. Anthoxanthum odoratum	FACU	5	4
5. Vicia sativa var. sativa	NOL	5	4
6. Rumex crispus	FAC+	3	2
7.			
8.			
9.			
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 0%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☐ NO ☒ Comments: ____

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: Poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0 - 10"	10yr 4/3	Scarce, too faint	cobly fill
10 - 16"	2.5yr 4/3	7.5yr 5/8 F/F/D	

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☐ NO ☒ Comments: <2% redox

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☐ NO ☒ Comments: Fill may be reason for hydrology in SP13, but it is now the normal circumstance.

DETERMINATION

WETLAND? YES ☐ NO ☒ **Comments:** Fill is obvious, rectangular and easy to distingush where the wetland boundary conforms to the edges. May be necessary to confirm hydrology + soils in spring. Ultimately, this fill appears in photos to be old with fill between 1950 and 1960. Expanded between 1960 and 1967 torn down buildings by 1979.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 08/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Open Meadow Plot # SP15
Plot location: South of plots SP13 and SP14
Recent Weather: Mean temp 66~degrees, sunny, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☐ Soil ☒ Hydrology ☐ been significantly disturbed?
Explain: Possibly fill material, but not judged as recent.

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status/ Raw % Cover/ Rel % Cover		
1. Festuca arundinacea *	FAC-	90	86
2. Agrostis cf. tenuis *	FAC	10	10
3. Trifolium subterraneum*	UPL	5	5
4. Hypochaeris radicata	FACU	t	t
5. Hordeum jubatum	FAC	t	t
6. Rumex crispus	FAC+	t	t
7. Centaurea pratensis	NOL	t	t
8. Bellis perennis	NOL	t	t
9. Geranium dissectum	NOL	t	t
10. Myosotis discolor	FACW	t	t
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 33%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☐ NO ☒ Comments: Very subjective to weedy veg. data/need soils + hydrology to qualify Used all relatively abundant species to make determination

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: Poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0 - 9"	2.5yr 3/3	7.5yr 6/8 F/F/D	SCL
Refusal@ 9"			

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☒ Redox features within 10", (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☒ NO ☐ Comments: Refusal due to gravel and rock, soil mixed with some cobble. Redox suggests soils now hydric.

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☐ NO ☒ Comments: Slight topographic rise from swale and SP13. Need more data due to a typical soils/hydro.

DETERMINATION

WETLAND? YES ☐ NO ☒ **Comments:** Point taken to describe a slightly higher bench that runs east-west along the southern side of the swale described by SP13. Needto monitor hydrology + do further soil sampling in the spring if mandated to confirm a lack of hydrology..

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 08/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Open Meadow Plot # SP16
Plot location: Plot is located just southwest of SP15 within ditch along south edge of field
Recent Weather: Mean temp 66~degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: _____
Has Vegetation ☒ Soil ☐ Hydrology ☒ been significantly disturbed?
Explain: Atypical ditch somewhat void of vegetation...plot size too large and extended well outside of ditch.

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status/ Raw % Cover/ Rel % Cover		
1. Festuca arundinacea *	FAC-	80	68
2. Anthoxanthum odoratum *	FACU	15	13
3. Trifolium repens *	FACU+	10	8
4. Mentha pulegium *	OBL	10	8
5. Bellis perennis	FACU	3	3
6. Myosotis discolor	FACW	t	t
7. Poa annua	FAC	t	t
8. Dipsacus fullonum ssp sylvestris	NOL	t	t
9. Daucus carota	NOL	t	t
10. Linum bienne	NOL	t	t
11. Galium aparine	FACW+	t	t

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 25%
Other Hydrophytic Vegetation Indicators: see list of non-dominant species in herb stratum
Criteria Met? YES ☐ NO ☒ Comments: Veg, a typical + problematic plot extended too far out of bottom of ditch.

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: Poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0 - 5"	2.5yr 3/2	10yr 4/6 F/F/D	SCL
5 - 17"	2.5yr 4/2	10yr 6/8 C/M/D/matrix	CL

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): _____

Criteria Met? YES ☒ NO ☐ Comments: Redox significant starting at 6"

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: 7" Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☒ Drift Lines
- ☐ Sediment Deposits
- ☒ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☒ FAC-Neutral Test
- ☐ Other: _____

Criteria Met? YES ☒ NO ☐ Comments: Saturated w/in top 7" but dry below. [due to heavy clay.]

DETERMINATION

WETLAND? YES ☒ NO ☐ **Comments:** Plot taken to characterize a perimeter ditch running along the North side of houses at the southern edge of soccer field. Veg not strong, but atypical situation leades to BPJ that normal circumstances would exhibit more wetland vegetation and straight forward hydrology.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 08/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meierino/ Susie Holmes
Plant Community: Disturbed muddy seasonally emergent lowland Plot # SP17
Plot location: Plot is in a small lowland area within the middle of a roadbed where vegetation has persisted
Recent Weather: Mean temp 66~degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☒ Soil ☒ Hydrology ☐ been significantly disturbed?
Explain: Muddy ruts indicate recent traffic leading to compacted soils and disturbed ground

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status/ Raw % Cover/ Rel % Cover		
1. Glyceria occidentalis *	OBL	50	68
2. Lemna minor *	OBL	10	14
3. Ludwigia palustris *	OBL	8	11
4. Hordeum jubatum *	FAC	3	4
5. Festuca arundinacea *	FAC-	3	4
6. Veronica cf. peregrina	OBL	t	t
7. Plagiobothrys cf. figuratus	FACW	t	t
8. Mentha pulegium	OBL	t	t
9. Matricaria discoidea	NOL	t	t
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 80%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☒ NO ☐ Comments: ~35% devoid of vegetation, standing water 2-3".

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0-12"	2.5y 3/2	7.5yr 5/8 C/M/D	SCL

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☒ NO ☐ Comments: cracked soil surface along dried out margins. Atypical soils and hydrology due to compaction, used SP13 for reference

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: 3 Depth to Saturation: - Depth to free water: -

Primary Hydrology Indicators:
- ☒ Inundated
- ☐ Saturated in upper 12 inches
- ☒ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☒ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☒ NO ☐ Comments: 2-3" standing water in lowest area. Atypical hydrology referenced to SP13.

DETERMINATION

WETLAND? YES ☒ NO ☐ Comments: Disturbed road bed (2 track). North of this plot was filled before 70's w/ 1-3 feet which tapers into edge of this wetland.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 08/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Ash Woodland becomming Open Meadow Plot # SP18
Plot location: Plot is just east-southeast of SP17, and west of the western edge of westernmost fenced-off popcorn flower population
Recent Weather: Mean temp 66~degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☐ Soil ☐ Hydrology ☐ been significantly disturbed?
Explain: ____

VEGETATION

Tree Stratum

	Status/	Raw % Cover/	Rel % Cover
1. Fraxinus latifolia*	FACW	70	100
2.			
3.			

Sapling/Shrub Stratum

	Status/	Raw % Cover/	Rel % Cover
1. Fraxinus latifolia*	FACW	20	100
2. Rubus armeniacus	FACU-	t	t
3.			
4.			
5.			

Herb Stratum

	Status/	Raw % Cover/	Rel % Cover
1. Bromus cf. mollis *	UPL	35	38
2. Alopecurus pratensis *	FACW	25	27
3. Festuca arundinacea	FAC-	15	16
4. Vicia ct. disperma	UPL	5	5
5. Vicia sativa var. sativa	UPL	5	5
6. Galium aparine	FACW+	3	3
7. Trifolium repens	FACU+	3	3
8. Carex densa	OBL	t	t
9. Camassia quamash	FACW	t	t
10. Rumex crispus	FAC+	t	t
11. Juncus marginatus	UPL	t	t

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 75%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☒ NO ☐ Comments: Many other species occurred within the herb stratum as trace cover, normal circumstances would have exhibited mre WL speaces.

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* * abund./size/contrast/color/location (matrix or pores/peds)	Redox Depletions*	Texture
0 - 5"	2.5yr 3/2	7.5yr 6/8 C/M/D/Matrix		SCL
5 - 19"	2.5yr 3/2	10yr 5/6 C/M/D/Redox channels	10G 5/1 10%	SC
5-19"	2.5yr 3/2	10yr 5/6 C/M/D/Redox channels	10yr 2.5/1 30%	SC

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☒ Gleyed or low chroma colors
- ☒ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☒ NO ☐ Comments: This is probably a typical profile pre - 1930's.

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: 0 Depth to Saturation: 17" Depth to free water: 19"

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☒ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☒ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☒ NO ☐ Comments: ____

DETERMINATION

WETLAND? YES ☒ NO ☐ Comments: Plot taken within isolate ash stand within the north/central portion of the site. Used in conjunction with SP19 to define WL boundary defined by levee fill slope.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 08/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Open Meadow Plot # SP19
Plot location: Plot is just northeast and upland of SP18
Recent Weather: Mean temp 66~degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☒ Soil ☒ Hydrology ☒ been significantly disturbed?
Explain: Levee fill slope/basically non-soil

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status	Raw % Cover	Rel % Cover
1. Festuca arundinacea *	FAC-	70	46
2. Bromus cf. mollis *	UPL	40	26
3. Agrostis tenuis *	FAC	20	13
4. Lolium perenne	FACU	10	7
5. Alopecurus pratensis	FACW	5	3
6. Dactylis glomerata	FACU	5	3
7. Geranium dissectum	NOL	3	2
8. Vicia sativa var sativa	NOL	t	t
9. Rumex crispus	FAC+	t	t
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 33%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☐ NO ☒ Comments: FAC neutral test also confirms no dominant hydrophytic veg (33%). Weedy community typical of fill slope.

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations*	Redox Depletions*	Texture
		* abund./size/contrast/color/location (matrix or pores/peds)		

Refusal @ 2"

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☐ NO ☒ Comments: Atypical fill at 3" (approach of slopefill for levee), refusal due to slope/fill

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: unknown Depth to free water: unknown

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☐ NO ☒ Comments: ____

DETERMINATION

WETLAND? YES ☐ NO ☒ **Comments:** Plot taken to characterize levee slope.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 08/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Open Meadow Plot # SP20
Plot location: Plot is just northwest of northwest corner of rodeo and just south/upland of road across from wooded area of plot SP18
Recent Weather: Mean temp 66-degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: _____
Has Vegetation ☒ Soil ☐ Hydrology ☐ been significantly disturbed?
Explain: Vegetation moderately unflunced by recreational use of area as a rodeo arena viewing fenceline.

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status	Raw % Cover	Rel % Cover
1. Festuca arundinacea*	FAC-	90	63
2. Trifolium repens*	FACU+	18	13
3. Alopecurus pratensis*	FACW	15	11
4. Agrostis tenuis*	FAC	10	7
5. Bellis perennis	UPL	3	2
6. Lolium perenne	FAC	3	2
7. Medicago polymorpha	UPL	3	2
8.			
9.			
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 50%
Other Hydrophytic Vegetation Indicators: _____
Criteria Met? YES ☐ NO ☒ Comments: Vegetation problematic. Top 4 species used due to problematic weedy plot.

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: Poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0 - 8"	2.5yr 3/2		SCL
8 - 16"	2.5yr 3/1	10yr 7/8 C/F/Matrix	SCL

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☒ Gleyed or low chroma colors
- ☒ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): _____

Criteria Met? YES ☒ NO ☐ Comments: Soils very strongly characteristic of wetlands in this area.

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: _____

Criteria Met? YES ☐ NO ☒ Comments: Slight topograpic rise forces standing water away from rodeo boundary, but soils data very strongly suggests that this area is inundated regularly.

DETERMINATION

WETLAND? YES ☒ NO ☐ **Comments:** Best professional judgement based on soils only. Hydrology questionable and could be monitored in spring to confirm determination.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 08/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Open Meadow Plot # SP21
Plot location: Plot is east of rodeo area and just west/upland of dirt road
Recent Weather: Mean temp 66~degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☒ Soil ☐ Hydrology ☐ been significantly disturbed?
Explain: Area used recreationally and creates a weedy, disturbed vegetation layer.

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status/ Raw % Cover/ Rel % Cover		
1. Festuca arundinacea	FAC-	70	56
2. Alopecurus pratensis	FACW	20	16
3. Trifolium repens	FACU+	8	6
4. Medicago polymorpha	NOL	7	6
5. Agrostis tenuis	FAC	5	4
6. Bromus cf. mollis	UPL	5	4
7. Hordeum jubatum	FAC	5	4
8. Lolium perenne	FAC	5	4
9. Vicia cf. disperma	NOL	t	t
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 25%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☐ NO ☒ Comments: Fails FAC-Neutral, but vegetation problematic due to recreational use.

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0 - 8	2.5yr 3/2		SCL
8 - 16	2.5 yr 3/1	10yr 7/8 C/M/D/matrix	SCL

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☒ Gleyed or low chroma colors
- ☒ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☒ NO ☐ Comments: ____

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☐ NO ☒ Comments: Hydrology not detectable due to slight topographic rise as in sp20.

DETERMINATION

WETLAND? YES ☒ NO ☐ **Comments:** Plot taken to judge slight topographic rise adjancent rodeo grounds. BPJ based determination on soils, as veg. + hydrology were problematic. Soils data strongly suggests that wetlands are present within the plot.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 08/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Open Meadow Plot # SP22
Plot location: Plot is just NE of SP21 within mud pit area
Recent Weather: Mean temp 66~degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☒ Soil ☐ Hydrology ☐ been significantly disturbed?
Explain: Vegetation problematic due to adjacent land use and unsually dry season.

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status	Raw % Cover	Rel % Cover
1. Festuca arundinacea*	FAC-	40	42
2. Festuca myuros*	FACU	10	11
3. Juncus tenuis*	FACW	10	11
4. Medicago polymorpha*	UPL	15	16
5. Hordeum jubatum	FAC	5	5
6. Trifolium repens	FACU+	5	5
7. Bellis perennis	UPL	t	t
8. Glyceria occidentalis	OBL	t	t
9. Ranunculus occidentalis	FAC	t	t
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 25%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☐ NO ☒ Comments: Vegetation problematic due to unseasonbly low precp. and disturbed land use history.

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0 - 8	2.5yr 3/2		SCL
8 - 16	2.5 yr 3/1	10yr 7/8 C/M/D/matrix	SCL

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☒ Gleyed or low chroma colors
- ☒ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☒ NO ☐ Comments: ____

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☒ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☒ NO ☐ Comments: Obvious deep/ wide soil cracks

DETERMINATION

WETLAND? YES ☒ NO ☐ **Comments:** Determination based on soils and hydrology.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 08/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Open Meadow Plot # SP23
Plot location: Plot is in SW corner of rodeo arena area
Recent Weather: Mean temp 66~degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☒ Soil ☒ Hydrology ☒ been significantly disturbed?
Explain: Area used for rodeo, soils compressed by horses, veg. trampled, creates low point within rodeo.

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status/ Raw % Cover/ Rel % Cover		
1. Festuca arundinacea	FAC-	5	5
2. Glyceria occidentalis	OBL	100	95
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 100%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☒ NO ☐ Comments: Used only glyceria because it was almost a monoculture

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* * abund./size/contrast/color/location (matrix or pores/peds)	Redox Depletions*	Texture
0 - 8	2.5yr 3/2			SCL
8 - 16	2.5 yr 3/1	10yr 7/8	C/M/D/matrix	SC

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☒ Gleyed or low chroma colors
- ☒ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☒ NO ☐ Comments: ____

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☒ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☒ NO ☐ Comments: Soil is deeply and widely cracked

DETERMINATION

WETLAND? YES ☒ NO ☐ Comments: This plot defines the outer edge of the rodeo grounds which was highly cracked mud at the point when the survey was taken. Gate surrounding rodeo defines a boundary of the depression explicitly.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 10/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meierina/Susie Holmes
Plant Community: Open Meadow Plot # SP24
Plot location: Plot is just north,or upland, of SP25 and east of western flagged popcorn flower site
Recent Weather: Mean temp 66~degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☐ Soil ☐ Hydrology ☐ been significantly disturbed?
Explain: ____

VEGETATION

Tree Stratum
Total Plot Cover: __% 50%: __% 20%: __%
Status/ Raw % Cover/ Rel % Cover
1. ____
2. ____
3. ____

Sapling/Shrub Stratum
Total Plot Cover: __% 50%: __% 20%: __%
Status/ Raw % Cover/ Rel % Cover
1. ____
2. ____
3. ____
4. ____
5. ____

Herb Stratum
Total Plot Cover: __%50%: __% 20%: __% Status/ Raw % Cover/ Rel % Cover

1. Festuca arundinacea	FAC-	60	38
2. Anthoxanthum odoratum	FACU	50	32
3. Bromus sitchensis	FACU	30	19
4. Agrostis tenuis	FAC	10	6
5. Stellaria media	FACU	3	2
6. Medicago polymorpha	FACU	3	2
7. Juncus marginatus	FACU	t	t
8. Festuca myuros	FACU	t	t
9. Poa annua	FAC	t	t
10. Bellis perennis	FACU	t	t
11. ____			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 0%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☐ NO ☒ Comments: ____

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations * abund./size/contrast/color/location (matrix or pores/peds)	Redox Depletions *	Texture
0-8"	7.5YR 4/4	pinheads	none	loamy
refusal at 8"				

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☐ NO ☒ Comments: ____

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: 0" Depth to Saturation: N/A Depth to free water: N/A

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☐ NO ☒ Comments: ____

DETERMINATION

WETLAND? YES ☐ NO ☒ Comments:

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 10/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Open Meadow Plot # SP25
Plot location: Just south of plot SP24 in lowland wet area
Recent Weather: Mean temp 66~degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☐ Soil ☐ Hydrology ☐ been significantly disturbed?
Explain: ____

VEGETATION

Tree Stratum
Total Plot Cover: __% 50%: __% 20%: __%
Status/ Raw % Cover/ Rel % Cover
1. ____
2. ____
3. ____

Sapling/Shrub Stratum
Total Plot Cover: __% 50%: __% 20%: __%
Status/ Raw % Cover/ Rel % Cover
1. ____
2. ____
3. ____
4. ____
5. ____

Herb Stratum
Total Plot Cover: __% 50%: __% 20%: __%
Status/ Raw % Cover/ Rel % Cover

1. Carex densa	OBL	30	29
2. Juncus tenuis	FACW-	25	24
3. Festuca arundinacea	FAC-	20	19
4. Anthoxanthum odoratum	FACU	10	10
5. Glyceria occidentalis	OBL	15	14
6. Alopecurus pratensis	FACW	5	5
7. Medicago polymorpha	FACU	t	t
8. Trifolium repens	FACU	t	t
9. ____			
10. ____			
11. ____			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 100%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☒ NO ☐ Comments: ____

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* * abund./size/contrast/color/location (matrix or pores/peds)	Redox Depletions*	Texture
10-12"	10YR 2/1	None	None	Silty Clay Loam
12-16"	10YR 3/2	Low (5-10%) 10YR 5/8 Concretions in Matrix	None	Silty Clay Loam

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☒ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☐ NO ☐ Comments: ____

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: 0" Depth to Saturation: N/A Depth to free water: N/A

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☒ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☒ NO ☐ Comments: Drainage patterns visible from surface

DETERMINATION

WETLAND? YES ☒ NO ☐ Comments:

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 10/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Open Meadow Plot # SP26
Plot location: Southern edge of primary contiguous wetland
Recent Weather: Mean temp 66~degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: _____
Has Vegetation ☒ Soil ☒ Hydrology ☒ been significantly disturbed?
Explain: Site is a mud pit with recent vehicle ruts

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status/ Raw % Cover/ Rel % Cover		
1. Glyceria occidentalis	OBL	100	100
2. Hordeum jubatum	FACW-	25	24
3. Trifolium repens	FAC-	20	19
4. Medicago polymorpha	FACU	10	10
5.			
6.			
7.			
8.			
9.			
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 100%
Other Hydrophytic Vegetation Indicators: _____
Criteria Met? YES ☒ NO ☐ Comments: Vegetation disturbed by vehicles, upland trace species only on mounds created by tire ruts

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0-6"	10 yr 3/2	10 yr 7/8 C/F/D/living roots	SCL
6-16"	2.5 y 2.5/1	10 y 2.5/1 C/F/D/pores	SCL

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): _____

Criteria Met? YES ☒ NO ☐ Comments: _____

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☒ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☒ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☒ FAC-Neutral Test
- ☐ Other: _____

Criteria Met? YES ☒ NO ☐ Comments: Hydrology increased in duration due to atypical situation. (vehicle ruts)

DETERMINATION

WETLAND? YES ☒ NO ☐ **Comments:** Internal depression localizes (BPJ) standing water further into the growing season. Plot was taken to establish wetland boundary on the south side. Soils are disturbed but still maintain a hydric profile that matches soil maps.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 10/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Open Meadow Plot # SP27
Plot location: Just south, or upland, of plot SP26 outside southern boundary of wetland area
Recent Weather: Mean temp 66~degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☒ Soil ☒ Hydrology ☒ been significantly disturbed?
Explain: fill for rail line/non-soil

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status	Raw % Cover	Rel % Cover
1. Festuca arundinacea*	FAC-	90	68
2. Vicia tetrasperma*	FACU	30	23
3. Trifolium repens	FACU	5	4
4. Anthoxanthum odoratum	FACU	5	4
5. Medicago polymorpha	FACU	3	2
6. Rumex crispus	FAC+	t	t
7. Dactylis glomerata	FACU	t	t
8.			
9.			
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 0%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☐ NO ☒ Comments: Highly a typical veg. due to fill material sub straight.

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations*	Redox Depletions*	Texture
		* abund./size/contrast/color/location (matrix or pores/peds)		
fill				

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☐ NO ☐ Comments: Atypical fill, not used to make determation.

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: 0 Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☐ NO ☒ Comments: ____

DETERMINATION

WETLAND? YES ☐ NO ☒ **Comments:** Area is filled recently along rail line fill. May need to monitor hydrology for directly adjacent hydrology to finalize determination (if necessary). Fill creates upland enviornment that may have recently been partially wetland.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 10/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Perimeter drainage ditch, disturbed road bed Plot # SP28
Plot location: Just north, or upland, of plot SP29 outside of ditch
Recent Weather: Mean temp 66-degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: _____
Has Vegetation ☒ Soil ☒ Hydrology ☒ been significantly disturbed?
Explain: Entire plot is within road bed of histroic rail line/non-soil.

VEGETATION

Tree Stratum

	Status/	Raw % Cover/	Rel % Cover
1.			
2.			
3.			

Sapling/Shrub Stratum

	Status/	Raw % Cover/	Rel % Cover
1.			
2.			
3.			
4.			
5.			

Herb Stratum

	Status/	Raw % Cover/	Rel % Cover
1. Festuca arundinacea*	FAC-	50	36
2. Medicago polymorpha*	FACU	40	29
3. Vicia tetrasperma*	FACU	20	14
4. Festuca myuros	FACU	10	7
5. Trifolium repens	FACU	10	7
6. Avena cf. barbata	FACU	10	7
7. Poa annua	FAC	t	t
8. Hypochaeris radicata	FACU	t	t
9.			
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 0%
Other Hydrophytic Vegetation Indicators: _____
Criteria Met? YES ☐ NO ☒ Comments: atypical weedy veg

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations*	Redox Depletions*	Texture
		* abund./size/contrast/color/location (matrix or pores/peds)		
Road bed fill				

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): _____

Criteria Met? YES ☐ NO ☒ Comments: non-soil

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: _____ Depth to Saturation: _____ Depth to free water: _____

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: _____

Criteria Met? YES ☐ NO ☒ Comments: Fill from rail line creates obvious ordinary high water line.

DETERMINATION

WETLAND? YES ☐ NO ☒ Comments: Fill for rail line very old, pre. 1972.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 10/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Perimeter drainage ditch Plot # SP29
Plot location: Within ditch along southern boundary, just south of SP29
Recent Weather: Mean temp 66~degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☐ Soil ☐ Hydrology ☐ been significantly disturbed?
Explain: ____

VEGETATION

Tree Stratum
Total Plot Cover: __% 50%: __% 20%: __%

	Status	Raw % Cover	Rel % Cover
1. Fraxinus latifolia*	FACW	10	100
2.			
3.			

Sapling/Shrub Stratum
Total Plot Cover: __% 50%: __% 20%: __%

	Status	Raw % Cover	Rel % Cover
1. Crataegus monogyna*	FACU+	20	61
2. Cytisus scoparius	FACU	5	15
3. Rubus armeniacus	FACU-	5	15
4. Prunus sp		3	9
5.			

Herb Stratum
Total Plot Cover: __% 50%: __% 20%: __%

	Status	Raw % Cover	Rel % Cover
1. Lemna minor*	OBL	25	37
2. Juncus patens*	FACW	15	22
3. Mentha pulegium	OBL	10	15
4. Centaurea pratensis	FACU	10	15
5. Carex deweyana	OBL	5	7
6. Anthoxanthum odoratum	FACU	3	4
7. Festuca arundinacea	FAC-	t	t
8. Dipsacus fullonum ssp. sylvestris	FAC	t	t
9. Polystichum munitum	FACU	t	t
10. Rumex crispus	FAC+	t	t
11. Epilobium ciliatum	FACW-	t	t

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 75%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☒ NO ☐ Comments: ____

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* * abund./size/contrast/color/location (matrix or pores/peds)	Redox Depletions*	Texture
0-7"	2.5Y 4/1	None	None	Silty Clay
refusal at 7"				

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☒ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☒ NO ☐ Comments:

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: 2" Depth to Saturation: N/A Depth to free water: N/A

Primary Hydrology Indicators:
- ☒ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☒ NO ☐ Comments: ____

DETERMINATION

WETLAND? YES ☒ NO ☐ Comments:

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 10/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Open Meadow Plot # SP30
Plot location: Eastern side of Ash Woodland within eastern side of site
Recent Weather: Mean temp 66~degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☒ Soil ☒ Hydrology ☒ been significantly disturbed?
Explain: Toe of a fill pile extends to this boundary

VEGETATION

Tree Stratum

	Status/	Raw % Cover/	Rel % Cover
1. Fraxinus latifolia *	FACU	40	100
2.			
3.			

Sapling/Shrub Stratum

	Status/	Raw % Cover/	Rel % Cover
1. Crataegus monogyna *	FACU+	30	100
2.			
3.			
4.			
5.			

Herb Stratum

	Status/	Raw % Cover/	Rel % Cover
1. Camassia quamash *	FACW	15	30
2. Mentha pulegium *	OBL	10	20
3. Juncus Pulegium *	FACW	20	40
4. Festuca arundinacea	FAC-	5	10
5. Unknown Grass		0	0
6.			
7.			
8.			
9.			
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 80%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☒ NO ☐ Comments: Adjacent plot in Ash Woodland more typical of this habitat composition.

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0-5"	2.5 y 3/1	F/F/F/matrix	SCL
5-16"	10 yr 3/1	5 yr 4/6 C/F/D/root channels	SCL

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☒ Gleyed or low chroma colors
- ☒ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☒ NO ☐ Comments: ____

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☒ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☒ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☒ NO ☐ Comments: ____

DETERMINATION

WETLAND? YES ☒ NO ☐ **Comments:** Plot taken to describe obvious fill most likely pre-1970's that extends into Ash Woodland when paired with SP 31.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 10/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Disturbed upland Plot # SP31
Plot location: Eastern side of upland area within Ash Woodland near eastern side of site
Recent Weather: Mean temp 66-degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☒ Soil ☒ Hydrology ☐ been significantly disturbed?
Explain: Obvious Fill

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status/ Raw % Cover/ Rel % Cover		
1. Festuca arundinacea*	FAC-	10	10
2. Rubus armeniacus*	FACU	15	15
3. Unknown Grass*		2	2
4. bare ground		73	73
5.			
6.			
7.			
8.			
9.			
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 0%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☐ NO ☒ Comments: Characterizes entire fill slope

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0-8"	2.5 YR 4/3	–	SL
>8"	Refusal	--	

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☐ NO ☒ Comments: ____

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☐ NO ☒ Comments: Fill pile extends above hydrology within the site

DETERMINATION

WETLAND? YES ☐ NO ☒ **Comments:** Plot taken to describe obvious fill pre-1985 that extends into Ash Woodland, characterized by Armenian blackberry and English hawthorn. When paired with SP 30

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 10/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Open Meadow Plot # SP32
Plot location: Within ditch along eastern boundary, just east of SP33
Recent Weather: Mean temp 66~degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☐ Soil ☐ Hydrology ☐ been significantly disturbed?
Explain: ____

VEGETATION

Tree Stratum

	Status/	Raw % Cover/	Rel % Cover
1. Fraxinus latifolia *	FACW	40	80
2. Crataegus monogyna *	FACU+	10	20
3.			

Sapling/Shrub Stratum

	Status/	Raw % Cover/	Rel % Cover
1. Rubus armeniacus *	FACU-	40	80
2. Prunus cerasiformis 'intermediate "'	FACU	10	20
3.			
4.			
5.			

Herb Stratum

	Status/	Raw % Cover/	Rel % Cover
1. Juncus patens *	FACW	80	89
2. Agrostis tenuis	FAC	10	11
3. Galium aparine	FACU	t	t
4. Vicia sativa var. sativa	FACU	t	t
5.			
6.			
7.			
8.			
9.			
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 66%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☒ NO ☐ Comments: This plot would not include most of the tree + shrub species if shaped along buttom of channel, plot domminated by FAC and greater ssp.

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* * abund./size/contrast/color/location (matrix or pores/peds)	Redox Depletions*	Texture
0-4"	10yr 3/2			SCL
4-8"	2.5yr 3/1	10yr 5/8 C/M/P		SC
8-20"""	10yr 4/1	10yr 5/6 C/F/D	(root channels	C

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☐ NO ☐ Comments: Depletions along root channels usu 10yr 4/1.

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☒ Drift Lines
- ☐ Sediment Deposits
- ☒ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☒ NO ☐ Comments: ____

DETERMINATION

WETLAND? YES ☒ NO ☐ Comments: Ditch appears to occur with road around 1960.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 10/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Open Meadow Plot # SP33
Plot location: Just west, or upland, of ditch and plot SP32
Recent Weather: Mean temp 66-degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☒ Soil ☒ Hydrology ☒ been significantly disturbed?
Explain: Old road bed, probably to access orchard east of ash stand created pre-1970's.

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status/ Raw % Cover/ Rel % Cover		
1. Festuca arundinacea*	FAC-	90	67
2. Avena fatua	FACU	10	7
3. Anthoxanthum odoratum	FACU	5	4
4. Vicia tetrasperma	FACU	t	t
5. Bellis perennis	FACU	t	t
6. Centaurea pratensis	FACU	t	t
7. Rumex crispus	FAC+	t	t
8. Rubus armeniacus*	FACU-	30	22
9.			
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 0%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☐ NO ☒ Comments: ____

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* * abund./size/contrast/color/location (matrix or pores/peds)	Redox Depletions*	Texture
0-6"	10yr 4/3		refusal @ 6"	

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☐ NO ☒ Comments: Histroic road bed [see below]

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☐ NO ☒ Comments: ____

DETERMINATION

WETLAND? YES ☐ NO ☒ **Comments:** Ditch appears on photos around 1960, edge of old roadbed highly disturbed with occassional remnants of red ore from fill.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 10/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Riparian edge of perimeter drainage ditch Plot # SP34
Plot location: Just south of waters edge along the northern edge of the property, see map
Recent Weather: Mean temp 66~degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: _____
Has Vegetation ☐ Soil ☒ Hydrology ☐ been significantly disturbed?
Explain: A typical soils impacted by

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/	Raw % Cover/	Rel % Cover
1. Rubus armeniacus *	FACU-	10	25
2. Salix cf. scouleriana *	FAC	10	25
3. Alnus rubra *	FAC	10	25
4. Crataegus monogyna	FACU	5	12
5. Toxicodendron diversilobum	FACU	5	12

Herb Stratum

	Status/	Raw % Cover/	Rel % Cover
1. Typha latifolia *	OBL	60	38
2. Camassia leichtlinii *	FACW-	25	16
3. Festuca arundinacea *	FAC-	30	19
4. Scirpus cf. acutis	OBL	10	6
5. Anthoxanthum odoratum	FACU	10	6
6. Equisetum arvense	FAC	10	6
7. Dactylis glomerata	FACU	5	3
8. Ranunculus uncinatus	FAC	5	3
9. Centaurea pratensis	FACU	5	3
10. Epilobium ciliatum	FACW-	t	t
11. Plantago lanceolata	FACU+	t	t

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 67%
Other Hydrophytic Vegetation Indicators: _____
Criteria Met? YES ☒ NO ☐ Comments: Plot was not shaped practically, therefore it captured many vegetation aspects up slope.

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* * abund./size/contrast/color/location (matrix or pores/peds)	Redox Depletions*	Texture
0-7"	10yr 3/1			SCL
7"	Fill [rock]			

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☒ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): _____

Criteria Met? YES ☒ NO ☐ Comments: Refusel @ 7" due to rock, probably associated with histroic dumping.

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: 0 Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☒ Drift Lines
- ☐ Sediment Deposits
- ☒ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☒ FAC-Neutral Test
- ☐ Other: sulfur odor

Criteria Met? YES ☒ NO ☐ Comments: Sulfuric odor when soil pit examed.

DETERMINATION

WETLAND? YES ☒ NO ☐ **Comments:** Plot taken to describe well defined boundary of Sutherlin Creek. Wetland boundary will defined by elevation gradient. Average of 9 feet emergent vegetation on each side of primary channel flow, completley within ordinary high water. Paired with SP 35.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 10/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Open meadow upland of riparian area Plot # SP35
Plot location: Just south , or upland, of plot SP34
Recent Weather: Mean temp 66~degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☒ Soil ☒ Hydrology ☒ been significantly disturbed?
Explain: Histroic, 1960's dike location dominated by gravel fill + side cast stream material.

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status/ Raw % Cover/ Rel % Cover		
1. Anthoxanthum odoratum*	FACU	70	61
2. Festuca arundinacea*	FAC-	20	17
3. Hypochaeris radicata	FACU	10	9
4. Centaurea pratensis	FACU	5	4
5. Bromus sitchensis	FACU	5	4
6. Daucus carota	FACU	5	4
7. Crysanthemum leucanthemum	FACU	t	t
8.			
9.			
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 0%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☐ NO ☒ Comments: ____

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly drained

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations*	Redox Depletions*	Texture
		* abund./size/contrast/color/location (matrix or pores/peds)		
Refusal @	surface			

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☐ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☐ NO ☒ Comments: A typical road fill

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☐ NO ☒ Comments: Well defined at top of dike.

DETERMINATION

WETLAND? YES ☐ NO ☒ Comments: Paired with SP 34 to define Sutherlin Creek. OHW is obvious below this plot.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 08/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Open Meadow Plot # SP36
Plot location: Plot is east of rodeo area and just west/upland of dirt road
Recent Weather: Mean temp 66~degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: ____
Has Vegetation ☒ Soil ☐ Hydrology ☒ been significantly disturbed?
Explain: Veg. and hydrology both impacted by rodeo grounds. Rodeo depression diverts some hydrology off of the distrubed plot.

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status	Raw % Cover	Rel % Cover
1. Festuca arundinacea*	FAC-	70	56
2. Alopecurus pratensis*	FACW	20	16
3. Trifolium repens	FACU+	8	6
4. Medicago polymorpha	NOL	7	6
5. Agrostis tenuis	FAC	5	4
6. Bromus cf. mollis	UPL	5	4
7. Hordeum jubatum	FAC	5	4
8. Lolium perenne	FAC	5	4
9. Vicia cf. disperma	NOL	t	t
10.			
11.			

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): 25%
Other Hydrophytic Vegetation Indicators: ____
Criteria Met? YES ☐ NO ☒ Comments: A typical veg. due to rodeo grounds operation. Would more than likely be hydrophytic if there was no atypical disturbance

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0 - 8	2.5yr 3/2		SCL
8 - 16	2.5 yr 3/1	10yr 7/8 C/M/D/matrix	SCL

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☒ Gleyed or low chroma colors
- ☒ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): ____

Criteria Met? YES ☒ NO ☐ Comments: Soils primary deteminant of wetland status.

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☐ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☐ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☐ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: ____

Criteria Met? YES ☐ NO ☒ Comments: Hydrology not detectable due to slight topographic rise from SP 23.

DETERMINATION

WETLAND? YES ☒ NO ☐ **Comments:** Plot establishes a typical wetlands adjacent to rodeo. Paried with SP23. Hydrology will need to be monitored if client wishes to provide evidence that wetlands aren't in this area.

DEPARTMENT OF STATE LANDS WETLAND DETERMINATION DATA FORM—Full Method

County: Douglas City: Sutherlin Date: 08/May/2007 File # 0349
Project/Contact: Sutherlin Parks/ Satre Associates, P.C. Det. by: Brian Meiering/ Susie Holmes
Plant Community: Open Meadow Plot # SP37
Plot location: Plot is east of rodeo area and just west/upland of dirt road
Recent Weather: Mean temp 66~degrees, partly cloudy, no percipitation, 0.74" month to date percipitation
Do normal environ. conditions exist? Y ☒ N ☐ If No, explain: _____
Has Vegetation ☒ Soil ☒ Hydrology ☐ been significantly disturbed?
Explain: Area affected by vehicular access. Barren of Vegetation.

VEGETATION

Tree Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	

Sapling/Shrub Stratum

	Status/ Raw % Cover/ Rel % Cover
1.	
2.	
3.	
4.	
5.	

Herb Stratum

	Status/ Raw % Cover/ Rel % Cover
1. Bare ground	100
2.	
3.	
4.	
5.	
6.	
7.	
8.	
9.	
10.	
11.	

Percent of Dominant Species that are OBL, FACW, FAC (not FAC-): __%
Other Hydrophytic Vegetation Indicators: _____
Criteria Met? YES ☐ NO ☒ Comments: _____

SOILS

Map Unit Name: 44A Conser silty clay loam Drainage Class: poorly

On Hydric Soils List? Y ☒ N ☐ Has hydric inclusions? Y ☐ N ☐

Depth Range of Horizon	Matrix Color	Redox Concentrations* / Redox Depletions* * abund./size/contrast/color/location (matrix or pores/peds)	Texture
0 - 8	10yr 3/2	7.5YR 5/8 C/M/D	SCL
8 - 16	10yr 3/2	7.5YR 5/8 C/F/D	CL

Hydric Soil Indicators:
- ☐ Histosol
- ☐ Histic Epipedon
- ☐ Sulfidic Odor
- ☐ Reducing Conditions (tests positive)
- ☐ Gleyed or low chroma colors
- ☒ Redox features within 10" (e.g., concentrations)
- ☐ Concretions/Nodules (w/in 3"; > 2mm)
- ☐ High organic content in surface (in Sandy Soils)
- ☐ Organic streaking (in Sandy Soils)
- ☐ Organic pan (in Sandy Soils)
- ☐ Listed on Hydric Soils List (and soil profile matches)
- ☐ Meets hydric soil criteria 3 or 4 (ponded or flooded for long duration)
- ☐ Supplemental indicator (e.g., NRCS field indicator): _____

Criteria Met? YES ☒ NO ☐ Comments: Soils disturbed within last year but hydric soil characteristics are evident

HYDROLOGY

Recorded Data
☒ Recorded Data Available ☒ Aerial Photos ☐ Stream gauge ☐ Other ☐ No Recorded Data Available

Field Data
Depth of inundation: None Depth to Saturation: None Depth to free water: None

Primary Hydrology Indicators:
- ☐ Inundated
- ☐ Saturated in upper 12 inches
- ☒ Water Marks
- ☐ Drift Lines
- ☐ Sediment Deposits
- ☒ Drainage Patterns

Secondary Hydrology Indicators (2 or more required):
- ☐ Oxidized Root Channels (upper 12")
- ☐ Water-stained Leaves
- ☒ Local Soil Survey Data
- ☐ FAC-Neutral Test
- ☐ Other: _____

Criteria Met? YES ☒ NO ☐ Comments: .

DETERMINATION

WETLAND? YES ☒ NO ☐ **Comments:** Plot establishes atypical disturbed conditions within Eastern field. Best professional judgement provides evidence that wetlands are present on-site unless proven otherwise by hydrology monitoring.

Ground Photo Point Locations: Sutherlin Festival Grounds

Legend

Photo Point | Study Area | Standard Plots

325 162.5 0 325 Feet

1 inch equals 325 feet

Appendix C: Ground Level Color Photographs

Begin February 6, 2007

PP1: Looking East across Plagiobothrys hirtus protection area



PP2: Looking SE towards SP6 and palustrine forsted ash stand.

PP3: Looking E from just N of SP26

PP4: Looking E from just E of SP27



PP4: Looking W from just E of SP27

PP5: Looking E from near center of field



PP6: Looking E from just SE of SP18

PP6: Looking NE from just SE of SP18



PP7: Looking E from just NE of SP18

PP8: Looking W from just N of SP17

PP8: Looking S from just N of SP17



PP9: Looking S from just just NW of SP20



PP9: Looking ESE from just just NW of SP20 (across SP20)

PP10: Looking W from just W of SP16



PP11: Looking W from SP9



PP12: Looking W along Sutherlin creek from footbridge

End February 6, 2007

Begin March 21, 2007

PP13: Looking W across SP1&SP2



PP14: Looking E along ditch (SP3 in foreground)



PP15: Looking E along property line just N of SP3



PP16: Looking NW over SP5(blue flag)

End March/Begin May 16, 2007 Photos

PP17: Looking E along the bottom of Sutherlin creek from SP34

PP18: Looking S over SP30 (Munsel book) and SP31 (Blue flag above fill)



PP19: Looking E from just S of SP25



PP20: Looking E across SP24 (left center)

PP21: Looking E across SP18 (just right of center)



PP21: Looking NE across SP19

PP22:Looking WNW across SP13(blue left) and SP14(blue right)

PP23: Looking SW across SP7 from SP8



PP24: Looking SW across SP12(foreground) and SP11(background)



PP25: Looking S across SP21

PP26: Looking E across SP32 from SP33



N

Legend

- Hydrology Sampling Points
- Study_Area

1 inch equals 300 feet

300 150 0 300 Feet

2008 Hydrology Monitoring Map
February-March 2008

2008 Hydrology Monitoring Data

Plot Number	Join	Installed y/n	Depth of Pit	Soil Notes	Hydrology Indicators	Hydric Soils	Depth to Hydric Soils Indicators	DATE	Surface Water y/n	Depth Of Surface Water (in)	Water In Pit y/n	Depth to Saturation	Depth to Water From Surface	Determination Y/N	Notes
1	1	N		----------		Y	---								
1	1	N		----------		Y	---								
1	1	N		----------		Y	---								
2	2	N		----------		Y	---								
2	2	N		----------		Y	---								
2	2	N		----------		Y	---								
3	3	N		----------		Y	---								
3	3	N		----------		Y	---								
3	3	N		----------		Y	---								
4	4	N		----------		Y	---								
4	4	N		----------		Y	---								
4	4	N		----------		Y	---								
5	5	Y	17"	----------	None	Y	---	2/20/2008	N	N/A	Y	--	16.0"	?	
5	5	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	6.0"	15.0"	Y	Irregular saturation due to fill, 6" nearest to surface
5	5	Y	17"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	6.0"	7.0"	Y	
6	6	N		----------		Y	---								
6	6	Y	12"	----------	None	Y	---	2/26/2008	N	N/A	N	NONE	N/A	N	Refusal at 12"
6	6	Y	16"	----------	None	Y	---	3/4/2008	N	N/A	N	NONE	N/A	N	Extremely hard fill
7	7	N		----------		Y	---								
7	7	N		----------		Y	---								
7	7	Y	20"	----------	water marks	Y	---	3/4/2008	N	N/A	Y	16"	16.5"	N	Same as SP10, appears to be irregularly inundated during storm events-water marks. Used BPJ.
8	8	N		----------		Y	---								
8	8	N		----------		Y	---								
8	8	N		----------		Y	---								

2008 Hydrology Monitoring Data

Plot Number	Join	Installed y/n	Depth of Pit	Soil Notes	Hydrology Indicators	Hydric Soils	Depth to Hydric Soils Indicators	DATE	Surface Water y/n	Depth Of Surface Water (in)	Water In Pit y/n	Depth to Saturation	Depth to Water From Surface	Determination Y/N	Notes
9	9	N		----------		Y	---								
9	9	N		----------		Y	---								
9	9	N		----------		Y	---								
10	10	N		----------		Y	---								
10	10	N		----------		Y	---								
10	10	N		----------		Y	---								
11	11	Y	15"	----------	None	Y	---	2/20/2008	N	N/A	Y	--	13.0"	?	
11	11	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	12.0"	13.0"	Y	
11	11	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	11"	12"	Y	
12	12	Y	16"	----------	None	Y	---	2/20/2008	N	N/A	N	NONE	N/A	N	
12	12	Y	16"	----------	None	Y	---	2/26/2008	N	N/A	N	NONE	N/A	N	
12	12	Y	16"	----------	None	Y	---	3/4/2008	N	N/A	N	NONE	N/A	N	
13	13	N		----------		Y	---								
13	13	N		----------		Y	---								
13	13	N		----------		Y	---								
14	14	N		----------		Y	---								
14	14	N		----------		Y	---								
14	14	N		----------		Y	---								
15	15	N		----------		Y	---								
15	15	N		----------		Y	---								
15	15	N		----------		Y	---								
16	16	N		----------		Y	---								
16	16	N		----------		Y	---								
16	16	N		----------		Y	---								

Plot Number	Join	Installed y/n	Depth of Pit	Soil Notes	Hydrology Indicators	Hydric Soils	Depth to Hydric Soils Indicators	DATE	Surface Water y/n	Depth Of Surface Water (in)	Water In Pit y/n	Depth to Saturation	Depth to Water From Surface	Determination Y/N	Notes
17	17	N		----------		Y	---								
17	17	N		----------		Y	---								
17	17	N		----------		Y	---								
18	18	N		----------		Y	---								
18	18	N		----------		Y	---								
18	18	N		----------		Y	---								
19	19	N		----------		Y	---								
19	19	N		----------		Y	---								
19	19	N		----------		Y	---								
20	20	Y	12"	----------	water within 12"	Y	---	2/20/2008	Y	0.01"	Y	surface	surface	Y	paired with H21 and previous plot data
20	20	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	0"	0.5"	Y	paired with H21 and previous plot data
20	20	Y	16"	----------	water within 12"	Y	---	3/4/2008	Y	0"	Y	surface	surface	Y	paired with H21 and previous plot data
21	21	Y	16"	----------	water within 12"	Y	---	2/20/2008	N	N/A	Y	7"	12.0"	Y	paired with H20
21	21	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	6.0"	7.0"	Y	paired with H20
21	21	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	8.0"	10"	Y	paired with H20
22	22	Y	16"	----------	water within 12"	Y	---	2/20/2008	N	N/A	Y	--	8.0"	Y	
22	22	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	2.5"	5.0"	Y	
22	22	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	2.0"	5.0"	Y	
23	23	Y	16"	----------	water within 12"	Y	---	2/20/2008	N	N/A	Y	--	12.0"	Y	
23	23	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	3.5"	5.5"	Y	
23	23	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	10"	13"	Y	
24	24	Y	16"	----------	water table within 12"	Y	---	2/20/2008	N	N/A	Y	6.0"	14.5"	Y	
24	24	Y	16"	----------	Inundation	Y	---	2/26/2008	N	N/A	Y	0.5"	0.5"	Y	
24	24	Y	16"	----------	Inundation	Y	---	3/4/2008	N	N/A	Y	7"	10"	Y	3" STANDING WATER 6" EAST OF HOLE

2008 Hydrology Monitoring Data

Plot Number	Join	Installed y/n	Depth of Pit	Soil Notes	Hydrology Indicators	Hydric Soils	Depth to Hydric Soils Indicators	DATE	Surface Water y/n	Depth Of Surface Water (in)	Water In Pit y/n	Depth to Saturation	Depth to Water From Surface	Determination Y/N	Notes
25	25	Y	23"	----------	None	Y	---	2/20/2008	N	N/A	Y	--	22.5"	Y	10" Fill, Check saturation
25	25	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	15.0"	16.0"	Y	Measured from top of hole. 10" OF FILL
25	25	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	15.0"	16.0"	Y	Measured from top of hole. 10" OF FILL
26	26	Y	16"	----------	inundation	Y	---	2/20/2008	Y	1.5"	N/A	N/A	N/A	Y	within arena
26	26	Y	16"	----------	inundation	Y	---	2/26/2008	Y	1.0"	N/A	N/A	N/A	Y	within arena
26	26	Y	16"	----------	inundation	Y	---	3/4/2008	Y	2.0"	N/A	N/A	N/A	Y	within arena
27	27	Y	16"	----------	None	Y	---	2/20/2008	N	N/A	Y	--	15.5"	?	Highly disturbed/ MIXED clay content
27	27	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	--	3.0"	Y	Highly disturbed/ MIXED clay content
27	27	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	1.0"	3.0"	Y	Highly disturbed/ MIXED clay content
28	28	Y	16"	----------	water within 12"	Y	---	2/20/2008	N	N/A	Y	--	9.5"	Y	
28	28	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	--	9.5"	Y	
28	28	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	7"	10"	Y	
29	29	Y	16"	----------	water within 12"	Y	---	2/20/2008	N	N/A	Y	--	10.5"	Y	
29	29	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	--	8.0"	Y	
29	29	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	4"	6"	Y	
30	30	Y	16"	----------	water within 12"	Y	---	2/20/2008	N	N/A	Y	--	11.5"	Y	
30	30	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	--	3.5"	Y	
30	30	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	surface	2"	Y	
31	31	Y	16"	----------	None	Y	---	2/20/2008	N	N/A	Y	--	13.0"	?	
31	31	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	--	3.0"	Y	
31	31	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	surface	2"	Y	
32	32	Y	16"	----------	None	Y	---	2/20/2008	N	N/A	Y	--	19.5"	?	
32	32	Y	16"	----------	None	Y	---	2/26/2008	N	N/A	N	N/A	N/A	N	
32	32	Y	16"	----------	None	Y	---	3/4/2008	N	N/A	Y	15"	18"	N	
33	33	N		----------		Y	---								
33	33	N		----------		Y	---								

Plot Number	Join	Installed y/n	Depth of Pit	Soil Notes	Hydrology Indicators	Hydric Soils	Depth to Hydric Soils Indicators	DATE	Surface Water y/n	Depth Of Surface Water (in)	Water In Pit y/n	Depth to Saturation	Depth to Water From Surface	Determination Y/N	Notes
33	33	N		----------		Y	---								
33	33	N		----------		Y	---								
34	34	N		----------		Y	---								
34	34	N		----------		Y	---								
34	34	N		----------		Y	---								
35	35	Y	16"	----------	saturation within 12"	Y	---	2/20/2008	N	N/A	Y	8.0"	16.0"	Y	Clay soils draw water upward a great deal
35	35	N	----------	----------	----------	Y	---	---	---	---	---	---	---	---------	Not Sampled
35	35	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	3"	5"	Y	
36	36	Y	20"	----------	None	Y	---	2/20/2008	N	N/A	N	N/A	N/A	N	paired with H35 to determine east west extent of wetland
36	36	N	----------	----------	----------	Y	---	---	---	---	---	---	---	---	Not Sampled
36	36	Y	20"	----------	None	Y	---	3/4/2008	N	N/A	N	N/A	N/A	N	paired with H35 to determine east west extent of wetland
37	37	Y	16"	----------	water within 12"	Y	---	2/20/2008	N	N/A	Y	--	7.0"	Y	
37	37	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	--	5.5"	Y	
37	37	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	4.5"	6.0"	Y	
38	38	Y	16"	----------	None	Y	---	2/20/2008	N	N/A	N	--	N/A	N	
38	38	Y	16"	----------	None	Y	---	2/26/2008	N	N/A	N	N/A	N/A	N	
38	38	Y	16"	----------	None	Y	---	3/4/2008	N	N/A	N	N/A	N/A	N	
39	39	Y	16"	----------	None	Y	---	2/20/2008	N	N/A	Y	--	16.5"	?	
39	39	Y	16"	----------	None	Y	---	2/26/2008	N	N/A	N	N/A	N/A	N	
39	39	Y	16"	----------	None	Y	---	3/4/2008	N	N/A	N	14"	16.5"	N	
40	40	Y	16"	----------	water within 12"	Y	---	2/20/2008	N	N/A	Y	--	10.0"	Y	
40	40	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	--	4.5"	Y	
40	40	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	3"	4"	Y	
41	97	Y	8"	----------	None*	N	---	2/20/2008	N	N/A	N	N/A	N/A	N	Same SP24; levee fill slope
41	97	Y	16"	----------	None		---	2/26/2008	N	N/A	N	N/A	N/A	N	Same SP24
41	97	N	---	----------	---	---	---	---	---	---	---	---	---	N	Same SP24, Levee fill slope.
42	98	Y	16"	----------	Drainage Patterns/See Veg Data	Y	---	2/20/2008	N	N/A	N*	--	--	?	Same as SP25; *Allow to fill Visit 2
42	98	Y	16"	----------	Drainage Patterns/See Veg Data	Y	---	2/26/2008	N	N/A	N	N/A	N/A	?	visible surface water marks, pit may be dry due to vehicle compaction of surrounding soils?

Plot Number	Join	Installed y/n	Depth of Pit	Soil Notes	Hydrology Indicators	Hydric Soils	Depth to Hydric Soils Indicators	DATE	Surface Water y/n	Depth Of Surface Water (in)	Water In Pit y/n	Depth to Saturation	Depth to Water From Surface	Determination Y/N	Notes
42	98	Y	16"	----------	Drainage Patterns/See Veg Data	Y	---	3/4/2008	N	N/A	N	N/A	N/A	?	Visible surface water marks, pit may be dry due to vehicle compaction of surrounding soils?
43	43	Y	7"	----------	Inundation	Y	---	2/20/2008	Y	2"	Y	surface	surface	Y	Same as SP29; single observation ok
43	43	N	--	--	--	--	--	--	--	--	--	--	--	--	No need to redo (Plot at base of ditch)
44	44	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	3.0"	3.5"	Y	Flagged, 25' @ 180 from H32
44	44	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	3.5"	6"	Y	Flagged, 25' @ 180 from H33
45	45	Y	16"	----------	None	Y	---	2/26/2008	N	N/A	N	13.0"	N/A	N	Not flagged, 20' @ 240 from H32
45	45	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	6"	9"	Y	Not flagged, 20' @ 240 from H33
46	46	Y	16"	----------	None	Y	---	2/26/2008	N	N/A	N	N/A	N/A	N	Not flagged, 28' @ 180 from H38
46	46	Y	24"	----------	None	Y	---	3/4/2008	N	N/A	Y	19"	21"	N	Fill approximately 10" sand/sandy loam
47	47	Y	16"	----------	None	Y	---	2/26/2008	N	N/A	N	N/A	N/A	N	Not flagged, 38'@ 360 from H38
47	47	Y	16"	----------	None	Y	---	3/4/2008	N	N/A	N	N/A	N/A	N	probable 12" sandy loam fill
48	48	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	6"	8"	Y	Not flagged, 32' @ 90 from H39
48	48	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	10.5"	11.0"	Y	Not flagged, 32' @ 90 from H39
49	49	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	11.0"	12.0"	Y	Not flagged, 35' @ 144 from H28
49	49	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	11"	12"	Y	Not flagged, 35' @ 144 from H28
50	50	Y	16"	----------	None	Y	---	2/26/2008	N	N/A	N	N/A	N/A	N	Not flagged, 65' @ 144 from H28, due west from ash tree
50	50	Y	16"	----------	None	Y	---	3/4/2008	N	N/A	Y	15"	16"	N	Probable fill of approximately 12" sandy loam
51	51	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	6.0"	15.0"	Y	Not flagged, 28' @ 180 from H98
51	51	Y	16"	----------	water within 12"	Y	---	3/4/2008	n	N/A	Y	6"	16"	Y	
52	52	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	7.0"	8.0"	Y	8' @ 360 from H20, immediately north of here it begins to slope up and refusal
52	52	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	4"	6"	Y	
53	53	Y	16"	----------	water within 12"	Y	---	2/26/2008	N	N/A	Y	10.0"	12.5"	Y	82' @ 270 from H20 & due south of telephone pole
53	53	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	7"	9"	Y	

Plot Number	Join	Installed y/n	Depth of Pit	Soil Notes	Hydrology Indicators	Hydric Soils	Depth to Hydric Soils Indicators	DATE	Surface Water y/n	Depth Of Surface Water (in)	Water In Pit y/n	Depth to Saturation	Depth to Water From Surface	Determination Y/N	Notes
54	54	Y	16"	----------	None	Y	---	2/26/2008	N	N/A	Y	14.0"	15.5"	N	105' @ 270 from H20
54	54	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	12"	12.5"	N	Borderline saturation/used BPJ
55	55	Y	16"	----------	None	Y	---	2/26/2008	N	N/A	Y	12.0"	13.0"	Y	Used BPJ. 82' @ 270 from H21 & due south of telephone pole, begins to slope up west from here into
55	55	Y	16"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	6"	8"	Y	
56	56	y	20"	----------	None	Y	---	3/4/2008	N	N/A	N	N/A	N/A	N	
57	57	Y	20"	----------	water within 12"	Y	---	3/4/2008	N	N/A	Y	4"	6"	Y	Same as SP20
58	58	Y	16"	----------	None	Y	---	3/4/2008	N	N/A	Y	10"	11"	Y	Tip of "duckbill" wetland near Soccer field

WETS Station : SUTHERLIN 4 NE, OR8760

*OBSERVED INCHES
ARE FROM ROSEBURG
CXUS56 KMFR
051000CF6RBG
PRELIMINARY LOCAL
CLIMATOLOGICAL
DATA (WS FORM: F-6)

Start 07 Water Year

Year	2006	2006	2006	2007	2007	2007	2007	2007	2007	2007	2007	2007
Month	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep
Observed (in.)	1.04	8.55	6.92	3.23	4.23	1.9	2.19	0.91	0.36	0.51	0.96	1.17
Average (in.)	2.98	6.33	6.25	5.73	5.46	4.22	3.53	2.66	1.43	0.64	0.78	1.32
Normal Variation	1.60-3.63	4.36-7.54	3.86-7.57	3.73-6.88	3.71-6.52	3.28-4.88	2.5-4.18	1.70-3.20	0.83-1.74	0.19-0.76	0.04-0.84	0.44-1.65
Percent of Average	34.9%	135.1%	110.7%	56.4%	77.5%	45.0%	62.0%	34.2%	25.2%	79.7%	123.1%	88.6%
Water YTD AVG	34.9%	103.0%	106.1%	92.7%	89.6%	83.5%	81.3%	78.0%	76.0%	76.1%	77.0%	77.4%

Min. Variance	1.6	4.36	3.86	3.73	3.71	3.28	2.5	1.7	0.83	0.19	0.04	0.44
Max Variance	3.63	7.54	7.57	6.88	6.52	4.88	4.18	3.2	1.74	0.76	0.84	1.65

Below Bar	1.38	1.97	2.39	2	1.75	0.94	1.03	0.96	0.6	0.45	0.74	0.88
Above Bar	0.65	1.21	1.32	1.15	1.06	0.66	0.65	0.54	0.31	0.12	0.06	0.33

Start 08 Water Year

*OBSERVED
INCHES ARE
FROM
ROSEBURG
CXUS56 KMFR
051000CF6RBG
PRELIMINARY
LOCAL
CLIMATOLOGIC
AL DATA (WS
FORM: F-6)

2007	2007	2007	2008	2008	2008	Water Year
Oct	Nov	Dec	Jan	Feb	Mar(04)	2008
3.7	4.27	5.82	8.73	1.84	0.15	24.51
2.98	6.33	6.25	5.73	5.46	4.22	30.97
1.60-3.63	4.36-7.54	3.86-7.57	3.73-6.88	3.71-6.52	3.28-4.88	
124.2%	67.5%	93.1%	152.4%	33.7%	3.6%	79.1%
124.2%	85.6%	88.6%	105.8%	91.1%	79.1%	

1.6	4.36	3.86	3.73	3.71	3.28
3.63	7.54	7.57	6.88	6.52	4.88

1.38	1.97	2.39	2	1.75	0.94
0.65	1.21	1.32	1.15	1.06	0.66



Updated 01 Feb 2008



Updated 01 Feb 2008

Appendix E: Literature Cited

REFERENCES AND LITERATURE CITED

1) *BLM addendum for Lower North Umpqua Watershed assessment : fifth field watershed .* Roseburg District BLM; 2003 July.

2) Carnate, John. City of Sutherlin. Pers comm., 2006-2007

3) Cooke, Sarah Spear. 1997. *A Field Guide to the Common Wetland Plants of Western Washington and Northwestern Oregon.* Seattle Audubon Society.

4) Geyer, Nancy A. Lower North Umpqua Watershed Assessment and Action Plan . Roseburg, Oregon: Prepared for the Umpqua Basin Watershed Council; 2003 July.

5) Guard, B. Jennifer. *Wetland Plants of Oregon and Washington.* Canada: Lone Pine Publishing, 1995.

6) Hitchcock, C. Leo and Cronquist, Arthur. *Flora of the Pacific Northwest.* Seattle: University of Washington Press, Seattle, 11th edition, 1998.

7) National Oceanic and Atmospheric Administration (NOAA). 2007-2008. Preliminary Climatology Data for Roseburg, Oregon. National Weather Service Forecast Office, Medford, Oregon. [Online] http://www.weather.gov/climate/

8) Pojar, Jim, and Andy MacKinnon. *Plants of the Pacific Northwest Coast: Washington, Oregon, British Columbia and Alaska.* Canada: B.C. Ministry of Forests and Lone Pine Publishing, 1994.

9) *Sutherlin Creek: Westslope Cutthroat* [map online]. Portland (OR) : StreamNet [6February2008].URL:<http://query.streamnet.org/Request.cfm?cmd=BuildQuery&NewQuery=BuildCriteria&Required=Run,County&DataCategory=23&County=111&ID=1233769433002&_Count=1>. Data Category = "Fish distribution"&"Fish barriers"

10) United States Department of Agriculture, Soil Conservation Service. *Hydric Soils in Douglas County Area, Oregon.* 1990.

11) United States Department of Agriculture, Natural Resource Conservation Service. *Soil Survey of Lane County Area, Oregon.* issued September 1987 (1981 data).

12) United States Department of the Army, Army Corps of Engineers, Waterways Experiment Station Environmental Laboratory. *Corps of Engineers Wetlands Delineation Manual, Technical Report Y-87-1.* January 1987.

13) United States Department of Agriculture, Natural Resources Conservation Service. 1996. WETS table documentation. Water and Climate Center, Portland, Oregon.

14) United States Fish and Wildlife Service, Cowardin, L.M., et. al., *Classification of Wetlands and Deepwater Habitats of the United States.* December 1979.

15) United States Fish and Wildlife Service, Reed, Porter B., *National List of Vascular Plant Species That Occur in Wetlands: Northwest (Region 9)*. 1988 Official Wetland Plant List & 1993 Supplement.

16) University of Oregon. *Aerial Photography Collection.* Public "Phase II" Aerial Series ftp order. <http://libweb.uoregon.edu/map/orephoto/consult.htm>

17) Whiting, A. 2001. Sutherlin creek watershed assessment. Salem, Oregon. Oregon Department of Environmental Quality.